



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20014541/Uqd3q2	
			Date: 13/01/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMD 4299D	Veh. Inspected	SKZ 8325T	
Policy No.	D20MTPV01016545	Coverage (\$)	0.00	
Claim No.	CMTD2003696/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	28/12/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W 316I (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WBA3A160X0NS36064	Colour	BLACK	
Odometer	147357 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	PIRELLI	6 mm	
L/H Front Tyre	225/45 R18	PIRELLI	6 mm	
R/H Rear Tyre	225/45 R18	PIRELLI	6 mm	
L/H Rear Tyre	225/45 R18	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	15/12/2020	Inspection Date	29/12/2020	
Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>2 Working Days</b>	