



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 1

Vehicle No. SKZ8325T BMW213I

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	FRONT HEADLAMP LH 17		2650.00	X
1	FRONT HEADLAMP TOP BRACKET LH 17		110.00	X
1	FRONT HEADLAMP LOWER BRACKET LH 17		110.00	X
1	FRONT BUMPER 617		1715.32 1880.00	X
1	FRONT BUMPER LOWER BEAM 17		185.00	X
1	FRONT BUMPER FOGLAMP LH 17		265.00	X
1	FRONT BUMPER FOGLAMP COVER LH 17		145.00	X
1	FRONT BUMPER SIDE RETAINER LH 17		65.00	X
1	FRONT FENDER LH R		535.00	X
1	FRONT FENDER SIGNAL LAMP LH 17		188.90	X
1	FRONT FENDER INNER SHEILD LH 17		157.60	X
		less	5% 6291.50	
			314.58	5%
			5976.93	
	<u>SPECIAL NETT ITEMS</u>			
1 SET	FRONT HEADLAMP CLIPS 17		80.00	X
1 SET	FRONT BUMPER CLIPS 17		80.00	50
1	FRONT FENDER SEALANT 17		100.00	X
	Total Parts		6236.93	

Not Authorised
 29/12/20
 1/5 H 1500/
 2 days.
 Up the After repair

P-1384.14
 50%
 P-1314.93
 S.N- 50.00
 L- 530.00
 1894.93
 20%
 1815



ACE AUTOLUTION PTE LTD
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel:6702 4282 Fax:6702 4202

Vehicle No. SKZ8325T BMW213I

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)		SURVEYOR ADJUSTMENT	
	<u>PARTS (LIST ITEMS)</u>					
1	FRONT HEADLAMP WASHER NOZZLE	Cn MS		389.40	/	168.82
1	FRONT HEADLAMP WASHER NOZZLE BRACKET			101.00		
		less	5%	490.40		
				24.52	5%	
				465.88		
		Total Parts		465.88		



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SKZ8325T BMW213I

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1200.00	200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	300
3	To remove , fefix wiring system at accident damage areas and check for proper function	150.00	X
4	To perform anti-rust treatment on affected areas	100.00	11X
5	To clear fault code with diagnostic computer and reset to BMW specification .	150.00	} 30
6	To remove and replace front headlamp lh	150.00	
Labour Total :		2750.00	
TOTAL (PARTS & LABOUR) :		8986.93	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: