

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20014547/KTD3E2

Date: 31/03/2021

REFERENCE

Insured/Claimant: HASHIM BIN MOHD SALLEH Policy No: DMPCSNW00047522000

Date of Loss: 09/12/2020

Nature of Claim: OD

Claim No: SNM20D204841/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT3314R**

Make & Model: TOYOTA VIOS, 1.5 E (M)

Reg. Date: 16/09/2008 (Man. Year: 2008)

Colour: Silver

Engine Capacity: 1497 cc

Market Value/New Car Price: S\$17,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1NZX802774

Chassis No: MR053HY9305079525

Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: Kumho 8 mm

Rear Left Side: Kumho 8 mm

Front Right Side: Kumho 8 mm

Rear Right Side: Kumho 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	100.00	0.00	100.00	100.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	100.00	0.00	100.00	100.00
- Excess (S\$)	3,500.00	3,500.00	0.00	0.00
Nett Amount (S\$)	-3,400.00	-3,500.00	100.00	-2.94

INSPECTION

Date of Assignment: 28/12/2020

Date Inspected: 29/12/2020 Inspected At:

10 ANG MO KIO IND PARK 2A #01-04

Repairer : Cheng Hoe Motor Pte Ltd

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$17,000.00
OMV :	\$9,084.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$19,328.00
COE Rebate (2) :	\$9,084.00
Total Rebate (1) + (2) = :	\$9,084.00

The total amount incurred will be Market Value \$17,000.00 minus Total Rebate \$9,084.00 = \$7,916.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Mar 2021)
Parts:	143	TOYOTA VIOS 1.5 E (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT3314R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING (FROM TRAFFIC POLICE COMPOUND TO CHENG HOE,AMK) - BY KING DOLLY	New	100.00	0.00
Gross Labour Cost (\$\$)			100.00	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >