

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jenny Lew

Date: 31 Dec 2020

**Preliminary Advice**

Insured Vehicle No	: SKX5287A	Accident Date	: 21/12/2020
TP Vehicle No	: SBF7B	Assignment Date	: 28/12/2020
Make	: MINI COOPER S	Est. Duration of Repair	: 5
Date of Inspection	: 29/12/2020		
Inspection At	: EUROKARS HABITAT PTE LTD (HQ) 27A TANJONG PENJURU LEVEL 5 SINGAPORE 609042		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,399.35
Revised Amount	:S\$	4,947.29
Check Items (Estimated)	:S\$	3,680.48
Total	:S\$	8,627.77
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :