



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



China Taiping Insurance (Singapore) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 ATTN.: MOTOR CLAIMS FAX:		NAME: Ms Neo Pixie ADDRESS: 4 Frankel Walk Singapore 457996 TEL: Ms. Valerie @ 84844030		WIP: 41172 EXCESS: DATE: 24-Dec-20	
VEH NO:	SBF7B	DATE IN:		CONTACT PERSON:	JOB
CHASSIS NO:	WMWYW720903L21179	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY
MODEL:	Cooper S Countryman RHD	DATE REG.:	20-Jun-20	POLICY NO.:	

NATURE OF WORKS

Parts Description

S/NO	Parts Description	QTY		REVISED	PRICES
1	TAIL GATE <i>bt</i>	1	M41.00.7.389.404		\$ 1,368.18
2	TAILGATE WEATHERSTRIP <i>X s/c</i>	1	M41.00.7.389.407		\$ 177.58
3	SPINDLE DRIVE <i>X s/c</i>	2	M51.24.9.482.767		\$ 924.70
4	TAIL GATE LOCK <i>X s/c</i>	1	M51.24.7.464.411		\$ 163.80
5	CATCH BRACKET <i>X s/c</i>	1	M51.24.7.473.763		\$ 77.74
6	SOFT-CLOSE-AUTOMATIC <i>X s/c</i>	1	M51.24.7.411.831		\$ 636.61
7	SPOILER SUB SHELL <i>? X s/c</i>	1	M51.62.7.391.256		\$ 325.52
8	TORX SCREW WITH WASHER <i>ne</i>	5	M07.14.7.142.046		\$ 26.00
9	BLIND RIVET <i>ne</i>	8	B51.24.8.226.003		\$ 42.16
10	BLIND PLUG <i>ne</i>	8	B07.14.7.140.850		\$ 12.48
11	SET FELT STRIPE ADHESIVE <i>ne</i>	2	B51.45.2.353.024		\$ 128.06
12	SET OF FITTINGS FOR SPOILER <i>ne</i>	1	M51.62.7.480.745		\$ 53.76
13	EXPANDING NUT <i>ne</i>	4	B51.12.7.020.321		\$ 5.20
14	CHROME TRIM STRIP, <i>X s/c</i>	1	M51.13.7.389.453		\$ 96.92
15	MOUNT RAIL LH, <i>ne</i>	1	M51.13.7.389.451		\$ 71.44
16	MOUNT RAIL RH, <i>ne</i>	1	M51.13.7.389.452		\$ 71.44
17	EMBLEM REAR <i>X m</i>	1	M51.14.9.447.810		\$ 79.11
18	COOPER S <i>ne</i>	1	M51.14.2.755.618		\$ 71.24
19	LOGO "COUNTRYMAN" <i>ne</i>	1	M51.14.7.421.909		\$ 71.24
20	TAIL LIGHT CHROME RING LH, <i>X s/c</i>	1	M63.21.7.385.427		\$ 80.80
21	TAIL LIGHT CHROME RING RH, <i>X s/c</i>	1	M63.21.7.385.428		\$ 80.80
22	REAR BUMPER <i>de</i>	1	M51.12.7.389.377		\$ 2,255.11
23	REAR BUMPER SPOILER <i>cut</i>	1	M51.12.7.391.199		\$ 413.01
24	REAR BUMPER TOWING COVER <i>X s/c</i>	1	M51.12.7.389.350		\$ 80.34
25	MOUNT FOR SMART OPENER <i>? X s/c</i>	1	M51.12.7.401.870		\$ 59.22
26	ADAPTER FOR SMART OPENER <i>? X s/c</i>	1	M51.12.7.482.914		\$ 23.34
27	REAR BUMPER RETAINER GUIDE LH <i>? X s/c</i>	1	M51.12.7.389.357		\$ 258.63
28	REAR BUMPER RETAINER GUIDE RH <i>? X s/c</i>	1	M51.12.7.389.358		\$ 258.63
29	REAR TRIM PANEL RH <i>X s/c</i>	1	M51.12.7.391.206		\$ 156.59
30	REAR TRIM PANEL LH <i>X s/c</i>	1	M51.12.7.391.205		\$ 156.59
31	REAR BUMPER LOWER TRIM <i>scr</i>	1	M51.12.7.411.083		\$ 293.21
32	PLUG-IN NUT <i>ne</i>	8	B51.12.7.461.407		\$ 33.28
33	RIVET <i>ne</i>	4	M07.14.9.807.127		\$ 4.96
34	REAR BUMPER REINFORCEMENT <i>? bt</i>	1	M51.12.7.389.375		\$ 583.05

	REINFORCEMENT GASKET ? xnn	2	B51.12.7.300.789		\$	29.12
35	HEAT SHIELD INSULATION ? xnn	1	M51.48.7.391.380		\$	67.99
37	ULTRASONIC SENSOR ? xsvl	4	B66.20.9.274.427		\$	1,299.76
38	SENSOR GASKET nnn /	4	B66.20.9.283.203		\$	26.52
39	CONTROL UNIT FOR SMART OPENING ? xsvl	1	B61.35.7.932.682		\$	646.16
40	SENSOR WIRE FOR SMART OPENER TOP ? xsvl	1	M61.35.7.391.042		\$	60.19
41	SENSOR WIRE FOR SMART OPENER BOTTOM ? xsvl	1	B61.35.7.391.043		\$	60.19
42	PLUG, BLACK ? xnn	7	M52.20.8.133.466		\$	8.68
43		0	0		\$	-
44		0	0		\$	-
	TOTAL PARTS				\$	11,339.35
					\$	-
	TOTAL PARTS COST				\$	11,339.35
	Labour Description					
1	TO REPLACE REAR BUMPER, TAILGATE, REAR BUMPER REINFORCEMENT, LOWER SPOILER & ALL DAMAGE BODY PARTS. TO REPAIR REAR END PANEL & ALL AREAS AFFECTED BY THE ACCIDENT. @840			1680 /	\$	3,360.00
2	TO RESPRAY TAILGATE, REAR END PANEL. @800			800 /	\$	2,000.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			150 /	\$	250.00
4	TO TRANSFER THE TAILGATE DOOR MECHANISM.			NETT	\$	420.00
5	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.			NETT	\$	560.00
6	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.			NETT	\$	120.00
7	TO TRANSFER THE REVERSE SENSORS.			150 /	\$	400.00
8	TO TRANSFER THE REVERSE CAMERA.			100 /	\$	300.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			150 /	\$	250.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			200 /	\$	350.00
11	SUNDRIES.			NETT	\$	20 / 50.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL

TOTAL LABOUR	\$	-	\$	8,060.00
TOTAL PARTS	\$	-	\$	11,339.35
TOTAL	\$	-	\$	19,399.35
LESS EXCESS	\$	-	\$	-
TOTAL AFTER EXCESS	\$	-	\$	-
GST 7%	\$	-	\$	-
GRAND TOTAL	\$	-	\$	-