

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660 FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 26/12/2020

TP Veh Reg No: SLJ5115A

Estimate No: ES2091054/AMK

Date: 28 Dec 2020

Policy No: 5106050808-01

Veh Reg No: SGP9285T

Make/Model: TOYOTA VIOS 1.5E
 A

Chassis No: MR053HY4204213643

Engine No: 1NZX510118

Reg. Date: 29/12/2006

Estimate Repair Cost to Vehicle No :SGP9285T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	245.50	1 PC	245.50	✓
2 REAR BUMPER SIDE RETAINER	21.60	2 PC	43.20	✓
3 REAR BUMPER CLIP	4.50	5 PC	22.50	✓
4 TAILLAMP	165.70	2 PC	331.40	✓
5 TAILLAMP INNER GASKET	33.30	2 PC	66.60	✓
6 REAR BOOT	505.70	1 PC	505.70	✓
7 REAR BOOT INNER LOCK	82.30	1 PC	82.30	✓
8 REAR BOOT INNER RUBBER	59.70	1 PC	59.70	✓
9 REAR BOOT LOGO	42.70	1 PC	42.70	✓
10 REAR BOOT EMBLEM 'VIOS'	25.10	1 PC	25.10	✓
11 REAR BOOT EMBLEM '1.5'	25.10	1 PC	25.10	✓
12 REAR BOOT EMBLEM 'E'	25.10	1 PC	25.10	✓
13 REAR BOOT EMBLEM 'VVTI'	21.70	1 PC	21.70	✓
14 REAR END PANEL	721.60	1 PC	721.60	✓
15 REAR END PANEL INNER TOP GARNISH	87.80	1 PC	87.80	✓
16 REAR END PANEL INNER TOP GARNISH CLIP	4.50	2 PC	9.00	✓
17 REAR SPARE TYRE COMPARTMENT PANEL INNER TOP BOARD	61.70	1 PC	61.70	✓
			2,376.70	
			Less 25%	594.18
				1,782.53
Special Net				
18 REAR END PANEL SEALANT	40.00	1 PC	40.00	✓
19 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
20 REVERSE SENSOR	200.00	1 SET	200.00	✓
			275.00	275.00
Labour				
21 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, REAR BOOT & ATTACHMENTS, TAILLAMPS, TO CUT, WELD & RENEW REAR END PANEL, KNOCKING & REPAIR REAR SPARE TYRE PANEL, REAR FENDER & REALIGN THE SAME	950.00	1 PC	950.00	✓
22 PUTTY & RESPRAY REAR BUMPER, REVERSE SENSORS, REAR BOOT, REAR BOTH FENDERS, REAR END PANEL, REAR SPARE TYRE PANEL & ALL AFFECTED AREAS	1,000.00	1 LA	1,000.00	✓
23 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,010.00	2,010.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 26/12/2020

TP Veh Reg No: SLJ5115A

Estimate No: ES2091054/AMK

Date: 28 Dec 2020

Policy No: 5106050808-01

Veh Reg No: SGP9285T

Make/Model: TOYOTA VIOS 1.5E
A

Chassis No: MR053HY4204213643

Engine No: 1NZX510118

Reg. Date: 29/12/2006

Estimate Repair Cost to Vehicle No :SGP9285T

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
			Total	S\$ 4,067.53
			Add GST @ 7%	284.73
			Total Amount Payable	S\$ 4,352.26

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE