PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

22-Dec-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1156 L

| | | THE PROPERTY OF THE PROPERTY O | | |
|---------|--|--|----|--|
| 1 pc | Front n/s head lamp | | \$ | 1,028.00× 44 |
| 1 pc | Front bumper | | \$ | 531.00de |
| 1 pc | Front bumper emblem | | \$ | 44.00×111 |
| 2 pcs | Front bumper n/s & o/s side retainer | @ \$16.00 | | CHX 32.00 14 nor 16 |
| 1 pc | Front bumper n/s protector | | S | nn 51.00 × nn |
| 1 pc | Front n/s fog light cover | | \$ | 66.00×n1 |
| 1 pc | Front n/s wheel cover | | \$ | 116.00 |
| 1 pc | Front n/s fender | | \$ | 384.00 ht |
| 1 pc | Front n/s fender inner shield | | \$ | 120.00 de |
| | | | \$ | UNIVERSAL PROPERTY OF THE PARTY |
| | | Less 10% | ¢ | 2,372.00 1051 |
| | | LKK Auto Consultants hence notify | \$ | 237.20 945.90 |
| 0.01=== | | The Repairer of the following: | | 2,104.00 |
| S/NETT | | To resurvey before/after spray painting To display damaged part(s) during resurvey | | |
| 1 set | Front bumper clips | Parts prices are subject to confirmation | \$ | 48.0030 ne |
| 1 pc | Front n/s fender sticker | Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed | \$ | 30.00 mee |
| 1 set | Front n/s fender inner shield clips | Supplementary item(s) must be resurround and | | |
| | | is subject to final approval from Insurance Company | 1 | 28.00 ree |
| | Sundry | Acknowledged by Repairer Signature: | • | 50.00 800 |
| | To focus and adjust front n/s & o/s he | ad Patrios | 7 | 50.00 Km |
| | To check front n/s wheel alignment | | * | 60.00 X ny |
| | | 945.92 new the accident 88 | \$ | 80.00× 1n |
| | To labour charge for dismantle and ren damaged parts. Including knock-out, st | | | |
| | reshape and adjust of the same, etc | | 6 | 650.00 200 |
| | | 1663.90 | \$ | 650.00 & 00 |
| | To putty and spray painting on front bur | mper front n/s fender //5\$1300 | | |
| | | | \$ | 400.00400 |
| | To apply rustproofing on the repaired an | nd replaced panels. | \$ | 120.0030 |
| | (ALL THE BEENE | * | s | 3,600.80 650 |
| | (ALL THE REPAIR COSTS ARE SUBJ | JECTED TO GST) | • | 0,000.80 |
| | ANY UNFORESEEN DAMAGES. THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE TaufML 9799949 WE IK Resum after each | | | |
| | | | | esun after casis |
| | | 7 | | esury after ugain |
| | | · 2 dey | P | 22/12/20 6245/ |
| | | Home La Vi | 10 | 22/12/20 2248p. / hunto. com |
| | | Taufn | ~6 | / con equi |
| | | | | |