



# MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737986

HP: 98888885

## Estimation

Date: 28/12/2020

Vehicle: SML5654M

Make / Model: HONDA FIT

Chassis:

| No. | Description                                  | Unit | Unit Price  | Amount               |
|-----|----------------------------------------------|------|-------------|----------------------|
|     | Parts Replacement:                           |      |             |                      |
| 1   | FRONT BUMPER / CR4                           | 1    | \$ 898.00   | \$ 898.00 755        |
| 2   | FRONT BUMPER SIDE RETAINER / BR 12           | 1    | \$ 21.00    | \$ 42.00 ✓           |
| 3   | FRONT BUMPER SIDE GRILLE LH X Svc            | 1    | \$ 112.00   | \$ 224.00 X          |
| 4   | FRONT BUMPER LOWER COVER X Svc               | 1    | \$ 312.00   | \$ 312.00 X          |
| 5   | HEADLAMP LH / SCR                            | 1    | \$ 1,598.30 | \$ 1,598.30 1,170.60 |
| 6   | HEADLAMP LOWER BRACKET LH X Svc              | 1    | \$ 91.60    | \$ 91.60 X           |
| 7   | FRONT FENDER LH / PD                         | 1    | \$ 598.00   | \$ 598.00 406        |
| 8   | FRONT FENDER INNER SHIELD LH X Svc           | 1    | \$ 184.00   | \$ 184.00 X          |
| 9   | FRONT FENDER EMBLEM 'HYBRID' LH / NEC        | 1    | \$ 65.00    | \$ 65.00 ✓           |
| 10  | FRONT FENDER LAMP LH X Svc                   | 1    | \$ 68.00    | \$ 68.00 X           |
| 11  | FRONT FENDER QUARTER GLASS C/W MOULDING LH X | 1    | \$ 512.00   | \$ 512.00 X          |
| 12  | SIDE MIRROR LH X Svc                         | 1    | \$ 589.00   | \$ 589.00 X          |
| 13  | FRONT SHOCK ABSORBER LH X Svc                | 1    | \$ 456.00   | \$ 456.00 X          |
| 14  | FRONT KNUCKLE ARM X Svc                      | 1    | \$ 398.00   | \$ 398.00 X          |
| 15  | FRONT KNUCKLE ARM BEARING X Svc              | 1    | \$ 215.00   | \$ 215.00 X          |
| 16  | FRONT LOWER ARM X Svc                        | 1    | \$ 548.00   | \$ 548.00 X          |
|     |                                              |      |             | \$ 6,798.90 2,438.6  |
|     |                                              |      | Less 20%    | \$ 1,359.78 -20%     |
|     |                                              |      | Total       | \$ 5,439.12 1,950.88 |

|   |                                             |   |           |                 |
|---|---------------------------------------------|---|-----------|-----------------|
|   | S/Nett items:                               |   |           |                 |
| 1 | FRONT BUMPER CLIPS SET / Nec                | 1 | \$ 50.00  | \$ 50.00 30     |
| 2 | FRONT FENDER SEALANT X Svc                  | 1 | \$ 80.00  | \$ 80.00 X      |
| 3 | FRONT RIM LH X Svc                          | 1 | \$ 300.00 | \$ 300.00 X     |
| 4 | FRONT TYRE X Svc                            | 1 | \$ 150.00 | \$ 150.00 X     |
| 5 | FRONT WHEEL HUB CAP SET / cut               | 1 | \$ 200.00 | \$ 200.00 175   |
| 6 | FRONT FENDER QUARTER GLASS SEALANT LH X Svc | 1 | \$ 80.00  | \$ 80.00 X      |
| 7 | FRONT DOOR SEALANT X Svc                    | 2 | \$ 80.00  | \$ 160.00 X     |
|   |                                             |   |           | \$ 1,020.00 205 |
|   | Labour to:                                  |   |           |                 |
| 1 | TO CHECK ELECTRICAL WIRING                  | 1 | \$ 80.00  | \$ 80.00 30     |
| 2 | REMOVE AND REFIT FRONT DOOR GLASS           | 1 | \$ 80.00  | \$ 80.00 X      |
| 3 | REMOVE AND REFIT FRONT UNDERCARRIAGE        | 1 | \$ 400.00 | \$ 400.00 X     |
| 4 | TRANSFER FRONT DOOR MECHANISM               | 1 | \$ 150.00 | \$ 150.00 X     |
| 5 | REMOVE AND REFIT FRONT QUARTER GLASS        | 1 | \$ 80.00  | \$ 80.00 X      |
| 6 | RESET FAULT CODE                            | 1 | \$ 200.00 | \$ 200.00 X     |

|    |                                   |   |                          |             |     |
|----|-----------------------------------|---|--------------------------|-------------|-----|
|    | CONDUCT FULL WHEEL ALIGNMENT      | 1 | \$ 150.00                | \$ 150.00   | 60  |
| 8  | TO RESPRAY UNDERCOATING           | 1 | \$ 150.00                | \$ 150.00   | 40  |
| 9  | APPLY ANTI RUST ON AFFECTED AREAS | 1 | \$ 200.00                | \$ 200.00   | 40  |
| 10 | SPRAY PAINTING ON AFFECTED AREAS  | 1 | \$ 800.00                | \$ 800.00   | 400 |
| 11 | PANEL BEATING ON AFFECTED AREAS   | 1 | \$ 800.00                | \$ 800.00   | 400 |
|    |                                   |   |                          | \$ 3,090.00 | 970 |
|    |                                   |   |                          |             |     |
|    |                                   |   |                          |             |     |
|    |                                   |   | Parts Replacement Amount | \$ 6,459.12 |     |
|    |                                   |   | Total Amount for Labour  | \$ 3,090.00 |     |
|    |                                   |   | Total Amount             | \$ 9,549.12 |     |

Repair day - 3 days.

HS

After paint photo.

Sun Pin (LHK)

29/12/2020.

TP without prejudice

1,950.88  
205  
970  


---

3,125.88  
- 20%  


---

2,500.70

HS  
\$2,500  
3 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: