



REF: AG2/ 200145851K

ASSIGNMENT

SMP 1566P

Yr Regn:

09, 19

Mover



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S: AUTO & GENERAL INSURANCE (SINGAPORE)

190 CLEMENCEAU AVENUE

#03-01 SINGAPORE SHOPPING CENTRE

SINGAPORE 239924

TEL: 6221 2111

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 23/12/2020

TP Veh Reg No: SLU2239M

Estimate No: ES2000119

Date: 24 Dec 2020

Policy No:

Veh Reg No: SMP1566P

Make/Model: KIA CERATO 1.6(A)

SUNROOF

Chassis No: KNAF5416MK5050537

Engine No: G4FGKH745520

Reg. Date: 13/09/2019

Estimate Repair Cost to Vehicle No :SMP1566P

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR NUMBER PLATE	60.00	1 PC	60.00	X
2 REVERSE CAMERA	320.00	1 PC	320.00	X
3 REVERSE SENSOR CENTRE - LH	285.10	1 PC	285.10	X
4 REVERSE SENSOR CENTRE - RH	285.10	1 PC	285.10	X
5 REVERSE SENSOR CORNER - LH	285.10	1 PC	285.10	X
6 REVERSE SENSOR CORNER - RH	285.10	1 PC	285.10	X
7 SPARE WHEEL TOOL TRAY	195.00	1 PC	195.00	X
			1,715.40	1,715.40
Spare Parts				
8 BOOT EMBLEM 'CERATO'	91.00	1 PC	91.00	—
9 BOOT EMBLEM 'GT LINE'	92.00	1 PC	92.00	—
10 BOOT EMBLEM 'LOGO'	94.00	1 PC	94.00	—
11 BOOT HINGE - LH	128.00	1 PC	128.00	X
12 BOOT HINGE - RH	128.00	1 PC	128.00	X
13 BOOT REFLECTOR LH	765.00	1 PC	765.00	X
14 BOOT REFLECTOR RH	765.00	1 PC	765.00	X
15 REAR BUMPER SPONGE	205.90	1 PC	205.90	X
16 REAR BODY STICKER, BUMPER, BOOTLID & RH FENDER	1,200.00	1 PC	1,200.00	800.00
17 REAR BOOT LID	1,783.00	1 PC	1,783.00	—
18 REAR BOOT LID LOCK	228.00	1 PC	228.00	X
19 REAR BOOT LID WEATHERSTRIP	198.10	1 PC	198.10	—
20 REAR BUMPER	963.70	1 PC	963.70	—
21 REAR BUMPER BRACKET - LH	86.00	1 PC	86.00	—
22 REAR BUMPER BRACKET - RH	86.00	1 PC	86.00	—
23 REAR BUMPER CLIPS	48.00	1 SET	48.00	—
24 REAR BUMPER SIDE LAMP - LH	385.00	1 PC	385.00	X
25 REAR BUMPER SIDE LAMP - RH	385.00	1 PC	385.00	—
26 REAR BUMPER LOWER BRAKE - LH	20.00	1 PC	20.00	—
27 REAR BUMPER LOWER BRAKE - RH	20.00	1 PC	20.00	—
28 REAR BUMPER LOWER PAD	2,810.20	1 PC	2,810.20	1200.00
29 REAR BUMPER LOWER SIDE SPOILER - LH	285.90	1 PC	285.90	X
30 REAR BUMPER LOWER SIDE SPOILER - RH	285.90	1 PC	285.90	X
31 REAR BUMPER REFLECTOR - CENTRE LOWER	203.00	1 PC	203.00	X
32 REAR BUMPER REINFORCEMENT	485.10	1 PC	485.10	—
33 REAR BUMPER SIDE RETAINER - LH	84.00	1 PC	84.00	X
34 REAR BUMPER SIDE RETAINER - RH	84.00	1 PC	84.00	X



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteitd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S: AUTO & GENERAL INSURANCE (SINGAPORE)
190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924
TEL: 6221 2111
ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 23/12/2020
TP Veh Reg No: SLU2239M

Estimate No: ES2000119
Date: 24 Dec 2020
Policy No:
Veh Reg No: SMP1566P
Make/Model: KIA CERATO 1.6(A)
SUNROOF
Chassis No: KNAF5416MK5050537
Engine No: G4FGKH745520
Reg. Date: 13/09/2019

Estimate Repair Cost to Vehicle No :SMP1566P

Description	U/Price	Quantity	List Price	Amount
			SS	SS
35 REAR END PANEL <i>4P8-40</i>	722.30	1 PC	<i>R</i> 722.30	<i>✓</i>
36 REAR END PANEL TOP GARNISH	149.00	1 PC	<i>D.I</i> 149.00	<i>—</i>
37 REAR END PANEL TOP GARNISH CLIPS	28.00	1 SET	<i>R</i> 28.00	<i>—</i>
38 REAR EXHAUST MUFFLER	768.20	1 PC	<i>R</i> 768.20	<i>X</i>
39 REAR FENDER INNER GARNISH - LH	385.00	1 PC	<i>Su</i> 385.00	<i>X</i>
40 REAR FENDER INNER GARNISH - RH	385.00	1 PC	<i>Su</i> 385.00	<i>X</i>
41 REAR TAILLAMP - LH	878.00	1 PC	<i>Su</i> 878.00	<i>X</i>
42 REAR TAILLAMP - RH	878.00	1 PC	<i>Su</i> 878.00	<i>X</i>
43 REAR TAILLAMP PANEL - LH	264.60	1 PC	<i>R</i> 264.60	<i>X</i>
44 REAR TAILLAMP PANEL - RH	264.60	1 PC	<i>R</i> 264.60	<i>X</i>
45 REVERSE SENSOR BUZZER	185.20	1 PC	<i>CM</i> 185.20	<i>2</i>
46 SPARE WHEEL CARDBOARD	389.00	1 PC	<i>R</i> 389.00	<i>X</i>
47 SPARE WHEEL PANEL	1,490.00	1 PC	<i>R</i> 1,490.00	<i>X</i>
48 REAR TAILGATE REFLECTOR - CENTRE	220.15	1 PC	<i>Su</i> 220.15	<i>X</i>
			18,916.85	18,916.85
Labour				
49 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,800.00	1 JOB	1,800.00	<i>6001</i>
50 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,800.00	1 JOB	1,800.00	<i>6001</i>
51 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	150.00	1 JOB	150.00	<i>601</i>
52 TO REMOVE/RENEW EXHAUST MUFFLER.	80.00	1 JOB	80.00	<i>X</i>
53 TO CHECK WIRING FUNCTIONS.	50.00	1 JOB	50.00	<i>201</i>
			3,880.00	3,880.00