

ASS. REC. BY:

REF:

AGH 200145851K

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Yec Auto

of _____

Insured: _____

Policy No. _____


Claims No. C10008459/LA

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMP 1566P Yr Regn: 09, 1P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: KIA Cerato c.c. 1591

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 25821 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAF5416mk 5050537

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / Std / Rlm / STD A/Rlm or

Tyre Size: F: _____

R: 225/40ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 23/12/20 D.O.I. 29/12/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Got BZ

Kenneth confirmed LS \$5350 (Red \$19162.25, 78%)

Date/Time, File Pass to?

☐ : Prel. Report

1) 08/07 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

TP

Lump Sum H.B.K (\$ 5350

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopte ltd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S: AUTO & GENERAL INSURANCE (SINGAPORE)

190 CLEMENCEAU AVENUE
 #03-01 SINGAPORE SHOPPING CENTRE
 SINGAPORE 239924

TEL: 6221 2111

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 23/12/2020

TP Veh Reg No: SLU2239M

Estimate No: ES2000119

Date: 24 Dec 2020

Policy No:

Veh Reg No: SMP1566P

Make/Model: KIA CERATO 1.6(A)

SUNROOF

Chassis No: KNAF5416MK5050537

Engine No: G4FGKH745520

Reg. Date: 13/09/2019

Estimate Repair Cost to Vehicle No :SMP1566P

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 REAR NUMBER PLATE	60.00	1 PC	60.00 X	
2 REVERSE CAMERA	320.00	1 PC	320.00 X	
3 REVERSE SENSOR CENTRE - LH	285.10	1 PC	285.10 ?	
4 REVERSE SENSOR CENTRE - RH	285.10	1 PC	285.10 ?	
5 REVERSE SENSOR CORNER - LH	285.10	1 PC	285.10 X	
6 REVERSE SENSOR CORNER - RH	285.10	1 PC	285.10 X	
7 SPARE WHEEL TOOL TRAY	195.00	1 PC	195.00 X	
			1,715.40	1,715.40
Spare Parts				
8 BOOT EMBLEM 'CERATO'	91.00	1 PC	91.00 —	
9 BOOT EMBLEM 'GT LINE'	92.00	1 PC	92.00 —	
10 BOOT EMBLEM 'LOGO'	94.00	1 PC	94.00 —	
11 BOOT HINGE - LH	128.00	1 PC	128.00 X	
12 BOOT HINGE - RH	128.00	1 PC	128.00 X	
13 BOOT REFLECTOR LH	765.00	1 PC	765.00 X	
14 BOOT REFLECTOR RH	765.00	1 PC	765.00 X	
15 REAR BUMPER SPONGE	205.90	1 PC	205.90 ?	
16 REAR BODY STICKER,BUMPER,BOOTLID&RH FENDER	1,200.00	1 PC	1,200.00 ?	
17 REAR BOOT LID	1,783.00	1 PC	1,783.00 —	
18 REAR BOOT LID LOCK	228.00	1 PC	228.00 X	
19 REAR BOOT LID WEATHERSTRIP	198.10	1 PC	198.10 —	
20 REAR BUMPER	963.70	1 PC	963.70 —	
21 REAR BUMPER BRACKET - LH	86.00	1 PC	86.00 ?	
22 REAR BUMPER BRACKET - RH	86.00	1 PC	86.00 ?	
23 REAR BUMPER CLIPS	48.00	1 SET	48.00 —	
24 REAR BUMPER SIDE LAMP - LH	385.00	1 PC	385.00 X	
25 REAR BUMPER SIDE LAMP - RH	385.00	1 PC	385.00 ?	
26 REAR BUMPER LOWER BRAKE - LH	20.00	1 PC	20.00 ?	
27 REAR BUMPER LOWER BRAKE - RH	20.00	1 PC	20.00 ?	
28 REAR BUMPER LOWER PAD	2,810.20	1 PC	2,810.20 —	
29 REAR BUMPER LOWER SIDE SPOILER - LH	285.90	1 PC	285.90 X	
30 REAR BUMPER LOWER SIDE SPOILER - RH	285.90	1 PC	285.90 X	
31 REAR BUMPER REFLECTOR - CENTRE LOWER	203.00	1 PC	203.00 ?	
32 REAR BUMPER REINFORCEMENT	485.10	1 PC	485.10 —	
33 REAR BUMPER SIDE RETAINER - LH	84.00	1 PC	84.00 X	
34 REAR BUMPER SIDE RETAINER - RH	84.00	1 PC	84.00 X	



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S: AUTO & GENERAL INSURANCE (SINGAPORE)

190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2111

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 23/12/2020

TP Veh Reg No: SLU2239M

Estimate No: ES2000119

Date: 24 Dec 2020

Policy No:

Veh Reg No: SMP1566P

Make/Model: KIA CERATO 1.6(A)
SUNROOF

Chassis No: KNAF5416MK5050537

Engine No: G4FGKH745520

Reg. Date: 13/09/2019

Estimate Repair Cost to Vehicle No :SMP1566P

Description	U/Price	Quantity	List Price	Amount
			SS	SS
35 REAR END PANEL	722.30	1 PC	722.30	✓
36 REAR END PANEL TOP GARNISH	149.00	1 PC	149.00	✓
37 REAR END PANEL TOP GARNISH CLIPS	28.00	1 SET	28.00	✓
38 REAR EXHAUST MUFFLER	768.20	1 PC	768.20	?
39 REAR FENDER INNER GARNISH - LH	385.00	1 PC	385.00	X
40 REAR FENDER INNER GARNISH - RH	385.00	1 PC	385.00	X
41 REAR TAILLAMP - LH	878.00	1 PC	878.00	X
42 REAR TAILLAMP - RH	878.00	1 PC	878.00	X
43 REAR TAILLAMP PANEL - LH	264.60	1 PC	264.60	X
44 REAR TAILLAMP PANEL - RH	264.60	1 PC	264.60	X
45 REVERSE SENSOR BUZZER	185.20	1 PC	185.20	?
46 SPARE WHEEL CARDBOARD	389.00	1 PC	389.00	X
47 SPARE WHEEL PANEL	1,490.00	1 PC	1,490.00	X
48 REAR TAILGATE REFLECTOR - CENTRE	220.15	1 PC	220.15	X
			18,916.85	18,916.85
Labour				
49 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,800.00	1 JOB	1,800.00	600
50 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,800.00	1 JOB	1,800.00	600
51 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	150.00	1 JOB	150.00	60
52 TO REMOVE/RENEW EXHAUST MUFFLER.	80.00	1 JOB	80.00	?
53 TO CHECK WIRING FUNCTIONS.	50.00	1 JOB	50.00	20
			3,880.00	3,880.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 23/12/2020 17:10 (SGT)
Date of Accident 23/12/2020 07:40 (SGT)
Exact Location of Accident Sembawang, Singapore
Additional Location Information Sembawang Road & Yishun Avenue 3 Junction
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMP1566P

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner Yong Kim Meng Marcus
NRIC No SXXXX714Z
Email Address yongkxm15@gmail.com
Mobile Phone No (Phone) +65-96585776
Alternative Phone No +65-96585776

VEHICLE PARTICULARS

Manufacturer Kia
Model Cerato
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company AIG
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 1900159324
Cover Note Number -

DRIVER

Name of Driver Yong Kim Meng Marcus
NRIC No SXXXX714Z
Date Of Birth 22/06/1987
Occupation Outdoor

Date Of Driving Pass 09/07/2011
 Driving experience 9 YEARS AND 5 MONTHS
 Gender Male
 Mobile Number (Phone) +65-96585776
 Alt. Phone Number +65-96585776
 Email Address yongkxm15@gmail.com
 Address 23 Sembawang Crescent #06-05
 Address complement -
 Postcode 757054
 Is the driver the policyholder? Yes
 If No, Relationship of the Driver with the Insured -
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? Yes
 Was any injured conveyed to hospital by ambulance? No
 Was any other material or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name Ngiang Bi Shi Joven
 Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
 Police Station Name Bishan Neighbourhood Police Centre
 Police Station Phone No (Phone) +65-18005529999
 Alt. Police Station Phone No (Fax) +65-65561905
 Police Station Address 20 Bishan Street 23 Singapore 579757
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

Please refer to Police Report No. T/20201223/2047.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number SLU2239M
 Vehicle Manufacturer Subaru
 Vehicle Model R1
 Vehicle Variant -

SKETCH PLAN

(A) SMP1566P

(B) SLU2239M

(C) JRC5550



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

Police Report No: T/2020/223/2047

Kindly email my Gih Report to me & my workshop
Yee Auto Per Ltd yeeautopteltd@gmail.com

DECLARATION

I/We declare the foregoing particulars are true in every respect.


23 DEC 2020
Policyholder's Signature
Date & Time:


23 DEC 2020
Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: