

Our Job Ref No : 305441071
Date : 22.01.21

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. : SHC1162Z CTPL

23.12.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **AIG** --- **SLB995B**
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges
- Total for Part-By-Part Repair Cost**
- (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,400.00
Final Lumpsum Repair cost **\$1,400.00**

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Taufikh

Date : 27/1/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305441071
 REGN NO : SHC1162Z
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 29.06.2017
 DATE/TIME IN : 28.12.2020 09:30
 ACCIDENT DATE : 23.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2282-G	PRIG4 COVER REAR BUMPER%	1 L	458.60	25.00	343.95	de	
0002	04-01-0302-2267-G	PRIVC BUMPER PIECE	10 L	22.00	25.00	16.50	net	
0003	04-01-0302-2288-G	REINFORCEMENT SUB-ASSY RE	1 L	318.80	25.00	239.10	bz	
0004	04-01-0302-3937-G	PRIG4 RETAINER RR BUMPER	1 L	94.80	25.00	71.10	? Xnn	1,434.70
0005	04-01-0302-2965-G	FILLER-REAR BUMPER EXTENS	1 L	148.40	25.00	111.30	? Xnn	-25%
0006	09-01-0302-2005-A	PRIG4 REVERSE SENSOR ASSY	1 N	135.70	2.50-	135.70	mr	1,076.02
0007	04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1 L	552.60	25.00	414.45	de	+Net 135.70
0008	04-01-0302-2286-G	COVER REAR BUMPER-TOW HOO	1 L	82.70	25.00	62.02	de	1,211.72

SUB-TOTAL : 1,394.12

JOB NATURE

0000 L	PANEL BEATING	350.00	320	550
0001 23-502	SPRAYPAINT ON AFFECTED AREA	250.00	200	1,761.72
0002 20-22	REMOVE/REFIX REVERSE SENSOR	120.00	30-	-20%
				1,409.38

l/s1400
 2 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanpin 9741 5744
 work up 26/12/2020
 02 days
 4/5 Repair after repair \$1,400/-
 Tanpin C/Handover