

ADVANCE AUTO GARAGE

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE

SINGAPORE 417868

TEL: 90079247

TO	: LONPAC	DATE	: 28/12/2020
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT			
VEHICLE DETAILS			
VEHICLE NO	: SLX9056L	TP Lontac Xiao Tony	
VEHICLE MODEL	: HONDA FIT		
CHASSIS NO	: GK33408929		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT		:	XAVIER / 90079247

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMEBR PLATE LAMP <i>the new</i>	2	\$ 85.00	\$ 170.00
2	REAR BUMPER <i>Distorted</i>	1	\$ 492.70	\$ 492.70
3	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 25.00	\$ 50.00
4	REAR BUMPER CENTRE MOULDING <i>3 Dashed</i>	1	\$ 115.00	\$ 115.00
5	REAR BUMPER SIDE MOULDING	2	\$ 65.00	\$ 130.00
6	REAR END PANEL <i>Distorted</i>	1	\$ 366.00	\$ 366.00
7	REAR END PANEL TOP GARNISH <i>Del'd</i>	1	\$ 198.00	\$ 198.00
8	REAR END PANEL ANTENNA SENSOR <i>cracked</i>	1	\$ 125.40	\$ 125.40
9	REAR END PANEL BUZZER <i>cracked</i>	1	\$ 89.40	\$ 89.40
10	TAILLAMP <i>cracked</i>	2	\$ 325.00	\$ 650.00
11	TAILLAMP PANEL <i>Repair</i>	2	\$ 235.00	\$ 470.00
12	TAILGATE <i>Distorted</i>	1	\$ 845.20	\$ 845.20
13	TAILGATE LOCK <i>Distorted</i>	1	\$ 209.20	\$ 209.20
14	TAILGATE WEATHERSTRIPE <i>at</i>	1	\$ 166.80	\$ 166.80
15	TAILGATE INNER TRIM BOARD <i>cracked</i>	1	\$ 285.90	\$ 285.90
16	TAILGATE OUTER GARNISH <i>cracked</i>	1	\$ 288.20	\$ 288.20
17	TAILGATE LAMP <i>at</i>	2	\$ 280.50	\$ 561.00
18	TAILGATE WIPER ARM <i>at</i>	1	\$ 76.10	\$ 76.10
19	TAILGATE WIPER ARM COVER <i>at</i>	1	\$ 24.00	\$ 24.00
20	TAILGATE WIPER MOTOR <i>Dashed</i>	1	\$ 485.20	\$ 485.20
21	TAILGATE GLASS <i>Shattered</i>	1	\$ 1,050.20	\$ 1,050.20
22	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 89.40	\$ 89.40
23	REAR FENDER INNER TRIM <i>Del'd</i>	2	\$ 295.00	\$ 590.00
24	SPARE TYRE PANEL <i>Repair</i>	1	\$ 945.10	\$ 945.10
25	SPARE TYRE PANEL TOP COVER <i>Del'd</i>	1	\$ 299.80	\$ 299.80

26	SPARE TYRE PANEL TOOLS SPONGE TRAY <i>Behind</i>	1	\$	381.70	\$	381.70	✓
27	REAR EXHAUST PIPE <i>3x100</i>	1	\$	544.20	\$	544.20	✓
28	REAR EXHAUST MOUNTING <i>new</i>	1	\$	35.00	\$	35.00	✓
29	HONDA LOGO <i>3 new</i>	1	\$	38.50	\$	38.50	✓
30	FIT EMBLEM <i>new</i>	1	\$	42.90	\$	42.90	✓

TOTAL PRICE: \$ 9,814.90

LESS 20% \$ 1,962.98

SUB TOTAL PRICE: \$ 7,851.92

7650.60
6120.48

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 30.00	\$ 30.00	✓
2	REAR NUMBER PLATE HOLDER <i>Behind</i>	1	\$ 30.00	\$ 30.00	✓
3	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00	30
4	REVERSE SENSOR <i>Damaged</i>	1 SET	\$ 280.00	\$ 280.00	200
5	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00	✓
6	REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00	✓
7	TAILGATE INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00	30
8	TAILGATE GLASS SEALANT <i>3 new</i>	1 SET	\$ 60.00	\$ 60.00	✓
9	TAILGATE GLASS SOLAR FILM <i>3 new</i>	1	\$ 280.00	\$ 280.00	200
10	REAR FENDER INNER TRIM CLIPS <i>new</i>	2 SETS	\$ 30.00	\$ 60.00	30
11	REAR CAMERA <i>Damaged</i>	1	\$ 480.00	\$ 480.00	380

TOTAL: \$ 1,400.00

1070

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	1000	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	1000	
3	WIRING CHECK	\$ 100.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	60	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
6	TO REMOVE REAR CAMERA	\$ 100.00	50	
7	TO REMOVE UPHOLSTERY AND REAR SEAT	\$ 350.00	80	
8	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	80	
9	TO REMOVE TAILGATE GLASS	\$ 180.00	120	
10	TO REMOVE EXHAUST PIPE	\$ 150.00	X	
11	TO DO INTERIOR CLEANING & TO VACCUUM GLASS SHARDS	\$ 150.00	60	
12	TOWING FEES	\$ 60.00	✓	

TOTAL: \$ 4,690.00

2590

ESTIMATE REPORT

TOTAL PARTS COST: \$ 9,251.92

TOTAL LABOUR COST: \$ 4,690.00

TOTAL REPAIR COST: \$ 13,941.92

total: 9780.48

1/51 7.8k

07 Days.

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7.8k