

LKK - Jaslin

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

DATE 29/12/2020

MS First Capital Insurance Limited

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SLL6427H

1) 1 PC	FRONT BUMPER	Dis ✓	\$ 496.30	496.40 ✓
2) 10 PC	FRONT BUMPER CLIPS	rec ✓	\$	42.00 ✓
3) 1 PC	FRONT RH SIDE RETAINER	crn ✓	\$	193.10 ✓
4) 1 PC	FRONT RH FOG LAMP	garnish twi ✓	\$	68.10 ✓
5) 1 PC	FRONT RH HEADLAMP	scr ✓	\$ 848.70	948.70 ✓
6) 1 PC	FRONT RH STEP PANEL	garnish twi ✓	\$	152.70 ✓
7) 1 PC	FRONT RH DOOR (REPAIR)	R X	\$	- X
			\$	1,901.00
	LESS 25%		\$	(475.25)
			\$	1,425.75
08)	SPRAY PAINTING		\$	680.00 500
09)	LABOUR CHARGE		\$	480.00 400
10)	WIRING CHECK		\$	50.00 20
11)	TUFFCOAT		\$	11 80.00 X
12)	ART WORK o/s door		\$	11 280.00 150
			\$	2,995.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not added
L/S to 1900/
3 days
the 2nd after repair
p. 1600.90
25%
1350.67
2420.67