



Pte Ltd

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H
REPAIR PERFORMA INVOICE

FCI

Vehicle number	FBQ9501Z
Make / Model	YAMAHA AEROX
Chassis number	MH3SG4640LJ068541
Accident date	20/12/20
Reference	2012-45

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT RH FAIRING	250 450.00 int
1	FRONT RH INNER FAIRING	100 250.00 int
1	FRONT RH HEADLAMP	350.00 X n
1 SET	FRONT FORK	600.00 X n
1	ENGINE COVER	150.00 X n
1	EXHAUST COVER	180.00 X int
1	EXHAUST BRACKET	90.00 X n
1	EXHAUST SILENCER	700.00 X n
		530 2770.00
Less 10%		477 277.00
		2493.00
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	BOX	280 500.00 int
1	BOX BRACKET	250.00 X n
1 SET	GEAR SHIT SHAFT OIL SEAL	24.00 X n
2	FORK OIL SEAL	120.00 X
1 BOT	FORK OIL	60.00 X
Subtotal		460 954.00
Balance C/F		3447.00
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	TO CHECK WIRING SYSTEM	60.00 30
2	TO CHECK FORK ALIGNMENT	200.00 100
3	TO REALIGN BODY FRAME	350.00 X n
4	TO R&R SUSPENSION, HANDLE BAR, HEADLAMP & FAIRING	400.00 100
5	TO SPRAY FENDER, SIDE FAIRINGS AND AFFECTED AREAS	500.00 150
Subtotal		1510.00
Grand total		4957.00

742
+ 680
380
1852
- 20%
1481.60
~1500

Tanpin 97457744
His Repair after repair
Tanpin @ Intakawin

03 days
477
460
380
1317
4581050 #