Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)

Sent: Friday, 12 March 2021 8:59 AM

To: Lee, Ming-Yao

Subject: [SEEK MANDATE] - AIG ref: 8830591971SG // LKK ref : CC4/AIG20014612/R1pa3

[ACCIDENT INVOLVING GBB 1595J(AIG) / SKS 866M (TP) / OTHERS ON 26/12/2020]

AIG ref: **8830591971SG**

LKK ref: CC4/AIG20014612/R1pa3

Dear Sirs/Mdm,

ACCIDENT INVOLVING GBB 1595J(AIG) / SKS 866M (TP) / OTHERS ON 26/12/2020

We refer to the above matter.

This is a 4 vehicles chain collision whereby our insured was the last car. In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%. We have informed insured about third party claim and NCD issue.

We seek your approval to offer repairer "Volkswagen Group Singapore Pte Ltd" at \$31,495.73(all-in).

The summary is as follows: -

| | Amount Claimed | Amount Revised |
|--|----------------|---------------------------------|
| 1. Cost of Repair (w/GST) | \$ 44,230.41 | \$ 29,207.73 |
| 2. Loss of Rental (15days x \$120.00)(w/GST) | \$ 1,926.00 | \$ 1,926.00 (15days x \$120.00) |
| 3. LTA/GIA Search Fee | \$ 2.00 | \$ 2.00 |
| 4. IROAD Camera Video Recorder* | \$ 360.00 | \$ 360.00 |
| Total | \$ 46,518.41 | <u>\$ 31,495.73</u> |

Surveyor recommended 13 days for repair + 2Sunday = 15days

^{*}For IROAD camera, please refer to the photo 100 & 101 in Merimen to show the wire of the camera. The camera was damaged after the accident.

| Market Value | : \$ 91,500.00 (est) |
|--------------|----------------------|
| LTA Rebate | : \$ 63,396.00 (est) |
| Nett Value | : \$ 28,104.00 (est) |

All supporting documents had been uploaded in Merimen.

Kindly let us have your approval / instruction in Merimen.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com | Fax: 6741 4108 HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)