

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/1018/2020/NS
DATE : 29-Dec-20
WIP : 64387


6451.04

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.
YOUR INSURED VEH NO : SMP 1046 Z

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR VICTOR KOH
ADDRESS : 80 BAYSHORE ROAD
#05-27
SINGAPORE 469992
TELEPHONE : HP +65 90117477
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700006976-03
VEHICLE NO : SLP 2794 C
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 30/5/2017
ENGINE NO : CVN 038676
CHASSIS NO : WAUZZZF43HA162588
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Dec-20
PLACE OF ACCIDENT : 17E MOUNT SINAI RISE SINGAPORE 276913





PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 2794 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X
2	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	✓
3	TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER, AND RHS FRONT DOOR. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	1500
4	TO RESPRAY THS FRONT FENDER AND RHS FRONT DOOR.	\$ 2,300.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,852.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 2794 C

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT FENDER - RH <i>Dented</i>	\$	758.00 ✓	613.20
2 FRONT FENDER ATTACHMENT PARTS <i>xxx</i>	\$	200.00 ✓	
3 FRONT FENDER BRACE - RH FRONT <i>xxx</i>	\$	117.00 ✓	
4 FRONT FENDER BRACKET - RH <i>xxx</i>	\$	35.00 ✓	
5 FRONT FENDER CLOSING ELEMENT - RH <i>xxx</i>	\$	49.00 ✓	
6 WHEEL HOUSING LINER - RH <i>xxx</i>	\$	239.00 ✓	
7 WHEEL HOUSING LINER ATTACHMENT PARTS <i>xxx</i>	\$	90.00 ✓	
8 STONE CHIP GUARD <i>xxx</i>	\$	50.00 ✓	
9 TOP FENDER LEDGE COVER - UPPER <i>the new</i>	\$	31.00 ✓	
10 TOP FENDER LEDGE COVER - LOWER <i>the new</i>	\$	23.00 ✓	
11 FRONT DOOR - RH <i>Dented</i>	\$	2,354.00 ✓	2553.60
12 FRONT DOOR OUTER SEAL - RH <i>xxx</i>	NEC \$	203.00 ✓	164.00
13 BONDING AGENT <i>the new</i>	NEC \$	47.00 ✓	
14 CLEANING SOLUTION <i>the new</i>	NEC \$	65.00 ✓	
15 FRONT DOOR ATTACHMENT PARTS <i>xxx</i>	\$	870.00 ✓	
16 FRONT DOOR CATCH <i>the new</i>	\$	104.00 ✓	
17 TYRE PRESSURE DATA PLATE <i>NEC</i>	\$	37.00 ✓	29.84
18 SUNDRIES <i>NEC</i>	\$	200.00 ✓	1840
TOTAL SPARE PARTS	:	\$ 5,472.00	
TOTAL LABOUR CHARGES	:	\$ 5,852.00	
GRAND TOTAL	:	\$ 11,324.00	

* ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Aden
SURVEYED DATE : 30/12/20
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : the authorised, 05 days H.S.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT