

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

28-Dec-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6955 U

1 pc	Front n/s head lamp	\$	1,028.00 cur ✓
1 pc	Front bumper	\$	531.00 del ✓
1 pc	Front bumper emblem	\$	44.00 X
1 pc	Front bumper reinforcement	\$	328.00 X } nn
1 pc	Front bumper sponge	\$	110.00 X }
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	\$	32.00 X }
1 pc	Front bumper n/s protector	\$	51.00 cut ✓
1 pc	Front n/s fog light cover	\$	66.00 cut ✓
		\$	2,190.00 1676
		\$	219.00
		\$	1,971.00 1508.40
		\$	48.00 300 ✓
1 set	Front bumper clips	\$	30.00 del 60
1 pc	Front n/s fender sticker	\$	28.00 X nn
1 set	Front n/s fender inner shield clips	\$	50.00 10 del ✓
		\$	60.00 30
		\$	80.00 X nn
		\$	650.00 200 640
		\$	400.00 ✓
		\$	120.00 X nn
		\$	3,437.00

LKK Auto Consultants hence deduct 10%
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signatures:
Date:

Sundry

To focus and adjust front n/s & o/s head lamps

To check front n/s wheel alignment

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc

To putty and spray painting on front bumper, front n/s fender

To apply rustproofing on the repaired and replaced panels.

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Tanphie 97475749
wp' 29/12/20 2pm
Resurvey after repair
Tanphie Thompson
2 days