

iShare Auto Pte. Ltd.

Co. Reg No: 201939376R

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: ishareauto@gmail.com



DATE : 29.12.20

TO : **AIG** MOTOR CLAIMS DEPTS

VEHICLE NO : **SJX5462Y**

MODEL : **PROTON PERSONA**

DATE OF ACCIDENT : 25.12.20

TIME OF ACCIDENT : 21:30HRS

Cecilia.

PLICM6SNRAG260622

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dented</i>	1	\$ 460.00	\$ 460.00
2	REAR BUMPER REFLECTOR <i>New</i>	2	\$ 85.00	\$ 170.00
3	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 45.00	\$ 90.00
4	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 370.00	\$ 370.00
5	REAR NUMBER PLATE LAMP <i>New</i>	2	\$ 45.00	\$ 90.00
6	REAR NUMBER PLATE LAMP HOLDER GARNISH <i>New</i>	1	\$ 79.00	\$ 79.00
7	BOOTLID <i>Buckled</i>	1	\$ 890.00	\$ 890.00
8	BOOTLID EMBLEM 'PERSONA' <i>New</i>	1	\$ 50.00	\$ 50.00
9	BOOTLID EMBLEM 1.6 <i>New</i>	1	\$ 35.00	\$ 35.00
10	BOOTLID HINGE <i>New</i>	1	\$ 95.00	\$ 95.00
11	BOOTLID TOP LOCK <i>New</i>	1	\$ 120.00	\$ 120.00
12	BOOTLID LOWER LOCK <i>New</i>	1	\$ 35.00	\$ 35.00
13	BOOTLID WEATHERSTRIP <i>New</i>	1	\$ 130.00	\$ 130.00
14	TAILLAMP <i>New</i>	2	\$ 320.00	\$ 640.00
15	REAR FENDER INNER COWLING <i>New</i>	2	\$ 95.00	\$ 190.00
16	REAR END PANEL <i>Dented</i>	1	\$ 395.00	\$ 395.00
17	REAR END PANEL TOP GARNISH <i>New</i>	1	\$ 125.00	\$ 125.00
18	REAR FLOOR PANEL TOP BOARD <i>New</i>	1	\$ 195.00	\$ 195.00

2325
2092.50

TOTAL PRICE \$ 4,159.00
LESS 10% \$ 415.90
SUB TOTAL PRICE \$ 3,743.10

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Dented</i>	1	\$ 80.00	\$ 80.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJX5462Y**
 MODEL : **PROTON PERSONA**
 DATE OF ACCIDENT : 25.12.20
 TIME OF ACCIDENT : 21:30HRS

2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
3	REAR NUMBER PLATE LAMP HOLDER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>x</i>
4	BOOTLID SEALANT <i>Not a</i>	1	\$ 150.00	\$ 150.00	<i>x</i>
5	BOOTLID MOULDING CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>x</i>
6	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	<i>x</i>
7	REAR FENDER COWLING CLIP (SET) <i>part</i>	1	\$ 80.00	\$ 80.00	<i>x</i>
8	REAR FENDER INNER TRIM CLIP (SET) <i>part</i>	1	\$ 80.00	\$ 80.00	<i>x</i>
9	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	<i>20</i>
10	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00	<i>60.</i>
11	REVERSE SENSOR (SET) <i>used</i>	1	\$ 220.00	\$ 220.00	<i>20</i>

360 TOTAL \$ 1,010.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	<i>800</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 150.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	TRANSFER BOOTLID MECHANISM	\$ 60.00	<i>x</i>
8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	<i>x</i>
9	REMOVE AND REFIX REAR NUMBER PLATE AND RESEAL	\$ 150.00	<i>80</i>
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>x</i>

TOTAL \$4,000.00

1880

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SJX5462Y**
MODEL : **PROTON PERSONA**
DATE OF ACCIDENT : 25.12.20
TIME OF ACCIDENT : 21:30HRS

TOTAL PARTS COST : \$ 4,753.10
TOTAL LABOUR COST : \$ 4,000.00
TOTAL REPAIR COST : \$ 8,753.10

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR

MICHELLE

HP : 9856 4815

Adrian L
L/S 29/12/20
06 Days

total: 4332.50

L/S: 3.41C.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: