



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CHIA CHONG TAT, CLARENCE	Cust No/Name KCV11076/CHIA CHONG TAT, CLARENCE
BLK 224B SUMANG LANE	Reg No/Reg Date SMK7057D / 22/04/201
#11-129	Date In/Mileage / 0
SINGAPORE 822224	Chassis No GF7W0600937
Contact No	Engine No
	Make/Model MIT/GF7W994
	Colour/Trim

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV11076	CRDVCH	23/12/2020/ 15:54	QUK	282 / Kevin Leong	61136			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
E PNT88000							1280.00	
REPLACE FRONT BUMPER & AFFECTED AREA				642				
E PNT98000							1100.00	
PAINT WORK ON FRONT BUMPER PANEL				559				
M SUNDRY							100.00	
PERFORM RUST PREVENTION							120.00	
A 54900099							280.00	
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901							100.00	
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY							50.00	
TO APPLY ZERTONA COATING ON AFFECTED AREA								
M SUNDRY								
SUNDRIES								
M HEADLAMP ASSY, RH					1.00	1938.00	00.00	1938.00
M FACE, FR BUMPER					1.00	859.00	00.00	859.00
M BRACKET, FR BUMPER SIDE, RH					1.00	18.00	00.00	18.00
M EXTENSION, FR BUMPER (Black)					1.00	515.00	00.00	515.00
M GARNISH, FR BUMPER SIDE					1.00	220.00	00.00	220.00
M GARNISH, FR BUMPER SIDE					1.00	112.00	00.00	112.00
M GARNISH, FR BUMPER SIDE					1.00	48.00	00.00	48.00
M COVER, FR BUMPER (Silver)					1.00	359.00	00.00	359.00
M GARNISH, FR BUMPER, RH					1.00	48.00	00.00	48.00
M REINFORCEMENT, FR BUMPER					1.00	490.00	00.00	490.00
M REINF, FR BUMPER SIDE, RH					1.00	69.00	00.00	69.00
M REINFORCEMENT, FR BMRP SIDE					1.00	22.00	00.00	22.00
M REINF, FR BUMPER SIDE, LH					1.00	60.00	00.00	60.00
M BAR, FR BUMPER GUARD					1.00	130.00	00.00	130.00

Estimate

Steve CLKK)
11/1/21, 1230pm
3 days
P/P
Ry Rol SM

Estimate

LXX Auto Consultants hence notify
Confirm & accepted by:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

7% GST on 7918.00 554.26

Nett 7,918.00

Total Payable 8,472.26

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.


INSURANCE CO. : INDIA

Supplementary Parts For Registration No.: SMK 7057 D

<u>Material</u>		<u>Cost (\$)</u>
1	Grille assy, Radiator	548.00 / CUT
Total Taxable		548.00
7% GST		38.36
Grand total		<u>586.36</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD



LOI AI TING
SENIOR OFFICER - ADMIN
DID : 6568 45556 / 6568 4501
FAX : 6567 5258 / 6565 1240



Exceptional Journeys

Surveyor : STEVE LKK
Claim : TP INDIA
DOA : 23.12.2020
Emailed : 02.02.2021, 10.50am
Date Survey : 11.01.2021

VEHICLE NO : SMK 7057 D
MODEL : MIT OUTLANDER
WIP : 61136

Material	:	\$	<u>3,169.00</u>
Labour	:	\$	<u>1,710.00</u>
Sub-Total	:	\$	<u>4,879.00</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>4,879.00</u>
GST 7%	:	\$	<u>341.53</u>
Grand Total	:	\$	<u>5,220.53</u>
Finalise By/Date	:	<u>LOI / 02/02/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 3 WORKING DAYS + 2 Days (1) Weekends
+ 0 Days (0) Waiting surveyor
TOTAL DAYS REPAIR TOOK = 5

☒ TP claim SH 6074 E

☐ Claim GIA / LTA fee

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE PTE LTD MOTOR CLAIM DEPARTMENT 64 CECIL STREET #04-05 IOB BUILDING SINGAPORE 049711 Contact No	Cust No/Name KCV11076/CHIA CHONG TAT, CLARENCE Reg No/Reg Date SMK7057D / 22/04/2019 Date In/Mileage 12/01/2021/ 29425 Chassis/Package GF7W0600937 /DC17P(F) Engine No Make/Model MIT/GF7W994 Colour/Trim /
12/01/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	30/01/2021/ 10:54	TLK	260 / AiTing	61136			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								✓ 640.00
REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 550.00
E PNT98000								✓ 120.00
RESPRAY ON FRONT BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 280.00
A 54900099								✓ 100.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 20.00
A 10028901								
CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 100.00
M SUNDRY								✓ 20.00
APPLY ZERTONA COATING ON AFFECTED AREAS								
M SUNDRY								
SUNDRIES								
X	FACE,FR BUMPER				1.00	✓ 859.00	00.00	859.00
X	BRACKET,FR BUMPER SIDE,RH				1.00	✓ 18.00	00.00	18.00
X	EXTENSION,FR BUMPER				1.00	✓ 515.00	00.00	515.00
X	GARNISH,FR BUMPER SIDE				1.00	✓ 220.00	00.00	220.00
X	GARNISH,FR BUMPER SIDE				1.00	✓ 112.00	00.00	112.00
X	COVER,FR BUMPER				1.00	✓ 359.00	00.00	359.00
X	GARNISH,FR BUMPER,RH				1.00	✓ 48.00	00.00	48.00
X	REINFORCEMENT,FR BUMPER				1.00	? 490.00	00.00	490.00
X	GRILLE ASSY,RADIATOR	→ Supp			1.00	548.00	00.00	548.00
Z TEXT								
TP CLAIM INDIA SH6074E								
DOA : 23.12.20								
SURVEYOR STEVE LKK 11.01.21								
REPAIR 03 DAYS								

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,169.00	Nett	4,879.00
Labour	1,590.00	7% GST on	341.53
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	5,220.53
Sundry/Others	120.00		
Total(w/o GST)	4,879.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.