

COMFORT DELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: _____

INSURANCE: aigMODEL: Hyundai Ioniq (Rear)MVA: CHIANGVEHICLE NO.: SHB6635Z

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
1	Boot Lid			\$2,480.40	bt
1	Boot Lid Rubber			\$187.40	Xun
1	Boot Lid Hinge (LH/RH)		\$31.30	\$71.30	Ry
1	Boot Lid Lock Lower			\$51.30	Xun
1	Boot Lid 'H' Emblem			\$28.00	bt
1	Boot Lid Absorber (LH/RH)		\$86.70	\$173.40	Xun.
1	Emblem-Hybrid			\$24.30	net
1	Emblem-Ioniq			\$31.30	net
1	Antenna Assy-SMARTK			\$40.50	fine
1	Boot Lid Glass, Upper			\$907.20	Xun.
1	Boot Lid Glass, Lower			\$584.90	ang
2	Boot Lid Lamp(LH/RH)		\$794.40	\$1,588.80	Xun.
1	Boot Lid Trimboard			SVC X \$259.70	net
1	Licence Lamp (LH/RH)		\$42.65	\$85.30	Xun
1	Bootlid Garnish			\$36.10	Xun
1	Bootlid Lower Garnish			\$25.40	Xun
2	Tail lamp assy LH/RH		\$870.40	\$1,740.80	Xun.
1	Rear Bumper			\$459.40	de
1	Rear Bumper Reinforcement			\$394.80	era
1	Rear Bumper Reinforcement Bracket (LH/RH)		\$138.10	\$276.20	int
1	Rear Bumper Centre Moulding Assy			\$451.25	de
1	Rear Bumper Lower Centre Moulding Assy			\$155.00	Ry
1	Rear Bumper Side Bracket (LH/RH)		\$55.80	\$111.60	Xun.
10	Rear Bumper Cover Clips		\$2.20	SVC X \$22.00	net
1	Rear Bumper Under Centre Cover			\$225.00	Xun
1	Rear Bumper Reflector Lamp(LH/RH)		\$41.45	\$82.90	Xun
1	Rear Bumper Fog Lamp			\$201.50	era
1	Rear Bumper Towing Cover			\$98.80	Xun
1	Rear Bumper lip			\$123.85	Xun
1	Rear Fog Lamp			\$201.50	X Reported
SUB TOTAL				\$11,119.90	nn
LESS 20%				\$2,223.98	
DISCOUNTED TOTAL				\$8,895.92	5728.55
					20% 4582.84
1	Boot Lid Comfort Logo & Tel No. Sticker			\$60.00	Nett
1	Boot lid App Logo Sticker			\$40.00	Nett
1	Reverse sensor			\$180.00	Nett
1	Rear bumper mat			\$50.00	Nett
1	Rear No. Plate W/Holder			\$55.00	Nett
1	Rear Windscreen Sealant			\$46.00	Nett
SUB TOTAL				\$431.00	385
Labour Charge					
Panel Beating				\$1,200.00	300

