



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV16047/SEAH JIE-WEI, SHAUN (XIE JIEWEI)
	Reg No/Reg Date	EB120S / 22/09/202
	Date In/Mileage	28/12/2020/ 0
	Chassis No	MMBSTA13AMH000692
	Engine No	3A92UJP7568
	Make/Model	MIT/21MY ATTRAGE 1.2 CVT (E31)
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	29/12/2020/ 09:38	QUK	282 / Kevin Leong	61249			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1800.00
REPLACE FRT BUMPER, FRT RH FENDER & AFFECTED AREA								
REPAIR ON SUPPORT PANEL								
E PNT98000								1050.00
PAINT WORK ON FRT BUMPER, FRT RH FENDER & FRT SUPPORT PANEL								
M SUNDRY								40.00
PERFORM RUST PREVENTION								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								20.00
SUNDRIES								
M	HEADLAMP ASSY,RH				1.00	1697.00	23.00	1306.69
M	LAMP ASSY,FOG,FR LH				1.00	303.00	23.00	233.31
M	FACE,FR BUMPER				1.00	703.00	23.00	541.31
M	GRILLE ASSY,RADIATOR				1.00	597.00	23.00	459.69
M	MARK,THREE-DIA				1.00	53.00	23.00	40.81
M	GRILLE,FR UNDER				1.00	90.00	23.00	69.30
M	COVER,FR BUMPER GRILLE				1.00	157.00	23.00	120.89
M	GARNISH,FR BUMPER,RH				1.00	44.00	23.00	33.88
M	BRACKET,FR BUMPER SIDE,RH				1.00	8.00	23.00	6.16
M	GARNISH,FR BUMPER SIDE				1.00	120.00	23.00	92.40
M	GARNISH,FR BUMPER SIDE				1.00	168.00	23.00	129.36
M	AIR DAM,SIDE,FR RH				1.00	19.00	23.00	14.63
M	SHIELD,FR WHEELHOUSE,RH				1.00	98.00	23.00	75.46
M	FENDER,FR RH				1.00	428.00	23.00	329.56
M	TANK,WINDSHIELD WASHER				1.00	74.00	23.00	56.98
M	CAP,WASHER TANK FILLER				1.00	7.00	23.00	5.39
M	MOTOR,WINDSHIELD WASHER(*)				1.00	139.00	23.00	107.03
M	REINFORCEMENT,FR BUMPER				1.00	291.00	23.00	224.07
M	EMBLEM ECO				1.00	17.00	00.00	17.00

Confirm & accepted by

Nett	6,923.92
7% GST on	6923.92
Total Payable	7,408.59

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.