



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SM AUTOMOTIVE 1 KAKI BUKIT AVENUE 6 BLOCK D AUTOBAY #01-43 SINGAPORE 417883 ON BEHALF OF AIRME BIN MOHAMED			Ref: CS/TP20014636/Aqd3e2 Date: 21/01/2021 Code: TP440	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SJN 727U	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	28/12/2020	
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA RUSH	c.c	1495
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	J200E0020610	Colour	BLACK
	Odometer	126472 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	FALKEN	6 mm
	L/H Front Tyre	215/60 R16	FALKEN	6 mm
	R/H Rear Tyre	215/60 R16	FALKEN	6 mm
	L/H Rear Tyre	215/60 R16	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/12/2020	Inspection Date	28/12/2020
	Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	