

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk C, 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 20th July 2016

Estimate repair cost for vehicle no: SJN727U TOYOTA RUSH 1.5 X A '09

CHASSIS: J200E0020610

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$1,680.25
2	2	Rear Boot Lid Hinge <i>new</i>	\$121.50	\$243.00
3	1	Rear Boot Lid Rush Logo <i>new</i>		\$85.00
4	1	Rear Boot Lid Inner Lock <i>new</i>		\$509.10
5	1	Rear Boot Lid Inner Rubber <i>new</i>		\$229.10
6	1	Rear Boot Lid Inner Trim Board <i>new</i>		\$780.10
7	1	Rear Boot Lid Spare Tyre <i>new</i>		\$550.00
8	1	Rear Boot Lid Spare Tyre Rim <i>new</i>		\$850.00
9	1	Rear Boot Lid Spare Tyre Outer Cover <i>new</i>		\$1,459.30
10	1	Rear Boot Lid Spare Tyre Inner Cover <i>new</i>		\$535.10
11	1	Rear Boot Lid Spare Tyre Bracket <i>Bent</i>		\$365.10
12	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$67.20
13	2	Rear Tail Lamp <i>new</i>	\$456.10	\$912.20
14	1	Rear Bumper <i>Dented</i>		\$1,377.10
15	2	Rear Bumper Side Retainer <i>new</i>	\$84.20	\$168.40
16	1	Rear Bumper Number Plate <i>new</i>		\$50.00
17	2	Rear Bumper Number Plate Lamp <i>stacked</i>	\$87.50	\$175.00
18	1	Rear Bumper Reverse Sensor <i>new</i>		\$350.00
19	1	Rear Bumper Camera <i>new</i>		\$550.00
20	8	Rear Bumper Clips <i>new</i>	\$6.50	\$52.00
21	2	Rear Bumper Mud Shield <i>new</i>	\$282.00	\$564.00
22	8	Rear Bumper Mud Shield Clips <i>new</i>	\$6.50	\$52.00
23	1	Rear End Panel Outer <i>new</i>		\$945.36
24	1	Rear End Panel Inner <i>new</i>		\$1,069.92
25	1	Rear End Panel Top Garnish <i>new</i>		\$345.30
26	2	Rear Fender Inner Trim Board <i>new</i>	\$698.28	\$1,396.56
27	1	Rear Floor Panel <i>new</i>		\$1,177.32
28	1	Rear Floor Panel Top Cover <i>new</i>		\$555.80
29	1	Rear Floor Panel Sealant <i>new</i>		\$450.00

TP Direct Asia
Independent
Xiao Chen

490

748

1258

87.5

200/su

380/su

30

391

69278

30	1	Rear Exhaust	2 AP me		\$937.30	+
31	1	Rear Center Exhaust			\$1,471.52	+
32	1	Rear Exhaust Aluminium Cover			\$270.00	+
33	2	Rear Exhaust Mounting			\$61.00	\$122.00

Decorative Stickers New

7909.25

300 200.

Subtotal :- \$20,345.03

S.N: 780

Labour charges

5931-93

To remove & refit cushion	\$380.00	80
To remove & refit rear & center exhaust	\$380.00	+
To remove & refit rear camera	\$380.00	60
To remove & refit rear windscreen	\$120.00	✓
Gum	\$50.00	✓
To remove & refit reverse sensor	\$100.00	60
Towing Fee	\$100.00	+
To check wiring	\$100.00	30
Tuff kote	\$150.00	60
Panel Beating	\$2,000.00	1000
Spray Painting	\$1,800.00	1000

2460

Admin L
1/5 28/12/20

07 Dec

Subtotal :- \$5,560.00

Total:- \$25,905.03

Total: 9171.93

4/s 7.3k 7500

7.3k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: