



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO. : FBL1320H
MAKE/MODEL : YAM / SNIPER T150

NO. : 37446

DATE : 23/12/2020

CLAIM NO. : 11660

POLICY NO. :

FROM : RAYMOND

not Arthur
2hr
2/5 \$680
3 day
Whip H. Att. 12pm

LM only

(Page 1 of 5)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE MAIN STAND - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	11 6.00X
2	BAR HANDLE P/N: 57063 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	11 35.00X
3	BASKET FRONT (PLASTIC) P/N: 61692 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	102 one 14.00
4	BOX REAR (COOCASE) 50L P/N: 68298 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$296.00	280 296.00
5	BRACKET BOX REAR (GIVI) HEAVY DUTY P/N: 60810 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$126.00	307 126.00
6	CAP SWING ARM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	27 5.00
7	COLLAR LAMP SIGNAL REAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	11 1.50
8	COVER BAR HANDLE FRONT P/N: 57071 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	107 13.00
9	COVER FRONT (VYRM3) P/N: 57067 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$41.00	11 41.00X

*37446 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	COVER FRONT LOWER RH P/N: 57072 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00 X
11	COVER HANDLE UPPER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$41.00	41.00 X
12	COVER SIDE FRONT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	49.00 X
13	COVER TAIL RH P/N: 56362 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	49.00 X
14	DAMPER PLATE 1 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$4.50	9.00 X
15	DAMPER PLATE 2 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50 X
16	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$16.00	32.00 X
17	EMBLEM FRONT PANEL - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00 X
18	GRAPHIC 13 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50 X
19	GRAPHIC 14 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	3.00 X
20	GRAPHIC 15 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	3.00 X
21	GRAPHIC 16 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$1.50	3.00 X
22	GRAPHIC 19 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	30.00 X
23	GRAPHIC 2 P/N: 56365 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$4.50	4.50 X
24	GRAPHIC 4 P/N: 56363 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1.50 X

*37446 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	GRAPHIC 6 P/N: 56364 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	6.00 X
26	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	14.00	\$63.00	882.00
27	LAMP SIGNAL FRONT RH ASSY P/N: 56366 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00 X
28	LAMP SIGNAL REAR LH ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00
29	LIGHT PILOT FRONT P/N: 57053 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$168.00	168.00 X
30	MID NUT STEERING CONE P/N: 21077 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$9.00	18.00 X
31	MIRROR SET (AFTERMARKET) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00
32	MUDGUARD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	18.00
33	MUDGUARD FRONT (BLACK) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$56.00	56.00 X
34	NUT SPRING P/N: 51016 - (REPORTED BY MECHANIC)	REPLACE	3.00	\$1.50	4.50 X
35	PANEL INNER 2 P/N: 57058 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00 X
36	PANEL INNER FRONT 1 P/N: 57075 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00 X
37	PEDAL BRAKE P/N: 57087 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	45.00 X
38	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	30.00 10
39	PLUG BLIND - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	12.00 X

*37446 *

bizSAFE₃CERT NO.: 2002-1-0363
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
40	PROTECTOR EXHAUST - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	1/c sc 40.00 X
41	PROTECTOR EXHAUST CAP P/N: 57060 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	1/c sc 32.00 X
42	PULLER CHAIN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	sc 16.00 ?
43	RACE BALL 1 P/N: 26829 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	1 13.00 X
44	RACE BALL LOWER 2 P/N: 26828 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	1 13.00 X
45	RETAINER BALL BEARING P/N: 57083 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$20.00	1 20.00 X
46	RETAINER BALL BEARING - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6.00	1 6.00 X
47	RIVET P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1.50	1 1.50 X
48	SCREW P/N: 53718 - (REPORTED BY MECHANIC)	REPLACE	6.00	\$3.00	1 18.00 X
49	STAY LICENSE PLATE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	1 30.00 X
50	STAY MUDGUARD REAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	1 32.00 X
51	STEERING CONE CENTRE P/N: 57078 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	1 13.00 X
52	STEERING CONE LOWER P/N: 57080 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	1 13.00 X
53	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$20.00	1 20.00 X
54	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH	X	1.00	\$45.00	35 45.00

SUB TOTAL
GST @ 7 %

\$2,505.50
\$175.39

*37446 *

bizSAFE₃



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
GRAND TOTAL (SGD)					\$2,680.89

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-588.50

857.95

*37446 *

bizSAFE₃

