

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 26.12.2020

Time: 12:28:28

Page: 1

Note - 48

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305440964
 REGN NO : SHA1215R
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 15.12.2016
 DATE/TIME IN : 25.12.2020 11:05
 ACCIDENT DATE : 24.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 04-01-0103-0579-G I40VC COVER ASSY-RR BUMPE	1		1,106.00	20.00	884.80
0002 04-01-0101-0111-G HYUNDAI BUMPER COVER CLIP	10	L	22.00	20.00	17.60
0003 04-01-0103-1150-A I40VC PROTECTOR MAT	1		50.00	2.00-	50.00
SUB-TOTAL :					952.40

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	200
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30
0003 20-05	RENEW ADVERTISMENT STICKER-Bumper	50.00	700
0004 20-05	RENEW ADVERTISMENT STICKER-Fender	200.00	
SUB-TOTAL :		930.00	1212.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

work done
 Tanjun 9742 5745
 26/12/20 4pm
 02 days
 Ls Resurvey after repair
 further information

4/1350
 * 02 days