



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                               |  |                           |                            |                |
|---|--|---------------------------|----------------------------|----------------|
| SOMPO INSURANCE SINGAPORE PL<br>50 RAFFLES PLACE #03-03<br>SINGAPORE LAND TOWERSINGAPORE 048623 |  |                           | Ref: CS/SMO20014665/Utd3q2 |                |
|   |  |                           | Date: 11/01/2021           |                |
|   |  |                           | Code: SMO                  |                |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |                           |                            |                |
|   | <b>Insured Veh.</b>  | FBP 5086L                 | <b>Veh. Inspected</b>      | SJK 8892M      |
|   | <b>Policy No.</b>  | D20MTMC01002593           | <b>Coverage (\$)</b>       | 0.00           |
|   | <b>Claim No.</b>   | CMTD2003822/MYE           | <b>Excess (\$)</b>         | 0.00           |
|   | <b>Assign From</b>   | GRACE TEO                 | <b>Assign Date</b>         | 29/12/2020     |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |                           |                            |                |
|   | <b>Make &amp; Model</b>  | HONDA VEZEL HYBRID (A)    | <b>c.c</b>                 | 1496           |
|   | <b>Engine No.</b>  | HIDDEN                    | <b>Year of Reg.</b>        | 2017           |
|   | <b>Chassis No.</b>   | RU31217178                | <b>Colour</b>              | BLUE           |
|   | <b>Odometer</b>  | 99631 KM                  | <b>Steering</b>            | IN ORDER       |
|   | <b>Brakes</b>  | IN ORDER                  | <b>Modification</b>        | SPORTS RIM     |
|   | <b>General</b>   | GOOD                      |                            |                |
| <b>3. Conditions of Tyres</b>   |  |                           |                            |                |
|   |  | <b>Size</b>               | <b>Make</b>                | <b>Balance</b> |
|   | <b>R/H Front Tyre</b>  | 215/60 R16                | YOKOHAMA                   | 6 mm           |
|   | <b>L/H Front Tyre</b>  | 215/60 R16                | YOKOHAMA                   | 6 mm           |
|   | <b>R/H Rear Tyre</b>   | 215/60 R16                | YOKOHAMA                   | 6 mm           |
|   | <b>L/H Rear Tyre</b>   | 215/60 R16                | YOKOHAMA                   | 6 mm           |
| <b>4. Description of Damages</b>  |  |                           |                            |                |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.<br><br>DAMAGES SEE DETAILS.   |                           |                            |                |
| <b>5. General Information</b>   |  |                           |                            |                |
|   | <b>Accident Date</b>   | 28/12/2020                | <b>Inspection Date</b>     | 30/12/2020     |
|   | <b>Survey held at</b>  | 60 JALAN LAM HUAT, #05-21 |                            |                |
|   | <b>Repairer</b>  | MY CAR CONSULTANT PTE LTD |                            |                |
| <b>5a. Remarks</b>  |  |                           |                            |                |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                           |                            |                |
| <b>5b. Estimate Days of Repair</b>  |  |                           |                            |                |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |                           | <b>4 Working Days</b>      |                |