

12/12/2020

REF: CS/SMO20014665/d3

Special Instruction:

ASS. REC. BY:

SURVEY BY:

ASSIGNMENT (Office)

From (Person): GRACE TEO

of

SMO

Date/Time: 29/12/2020@2PM

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJK 8892M

Insured: FBP 5086L

at Workshop m/s MY CAR CONSULTANT

Tel: 8866 8832

of 60 JALAN LAM HUAT# 05-21

Policy No:

Claim No: CMTD2003822/MYE

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A 28/12/2020

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 2.49PM@29/12/2020

Person Contacted: HUI QIN

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (☒) Estimate	Repairer agreed to survey on 30/12/2020
	SJK 8892M-X	
	FBP 5086L-X	