

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III20014666/ABA3Q2
Date: 17/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant Vehicle No :	GBG2911Y	Insured Vehicle No :	SHA6992Y	
Date of Loss:	22/12/2020	Nature of Claim:	TP	Claim No: MCT20120436

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG2911Y		Engine No:	1KD2626120
Make & Model:	TOYOTA HIACE, 3.0 D DX (M)		Chassis No:	KDH2010199523
Reg. Date:	17/07/2017 (Man. Year: 2016)		Odometer:	91857 km
Colour:	White			
Engine Capacity:	2982 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	CST TIRE 6 mm	Rear Left Side:	CST TIRE 6 mm
Front Right Side:	CST TIRE 6 mm	Rear Right Side:	CST TIRE 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,022.22	1,793.50	2,228.72	55.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,620.00	1,110.00	1,510.00	57.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,642.22	2,903.50	3,738.72	56.29
Approved Total (Overridden) (S\$)		2,300.00		

(S\$)	6,642.22	2,300.00	4,342.22	65.37
+ GST 7.00/7.00% (S\$)	464.96	161.00	303.96	65.37
Nett Amount (S\$)	7,107.18	2,461.00	4,646.18	65.37
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
(S\$)		2,961.00		
Liabie Amount (50.00%) (S\$)		1,480.50		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,487.95		
Global Sum Settlement (S\$)		1,450.00		

INSPECTION

Date of Assignment: 22/12/2020

Date Inspected: 22/12/2020

Inspected At:

MG Solution Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre
 Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2021)
Parts:	213	TOYOTA HIACE 3.0 D DX (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG2911Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SLIDING DOOR LH	Dented	1,855.60 FL	*1,655.00 FL
2	1		*REAR FENDER LH	Repair	2,355.90 FL	*- FL
3	1		*REAR BUMPER	Torn	680.00 FL	*568.00 FL
4	1		*REAR BUMPER SIDE RETAINER	N/S Necessary	124.80 FL	*35.00 FL
5	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
6	1		*RIM COVER	Cut	240.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,276.30	2,358.00
- List Item Discount on L Items 25.00/25.00% (S\$)	1,254.08	564.50
Total Parts (S\$)	4,022.22	1,793.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING AND REPLACE PARTS	New	1,200.00	500.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	500.00
3	TRANSFER SLIDING DOOR MECHANISM	New	140.00	60.00
4	TO REMOVE AND REFIX REVERSE SENSOR	New	80.00	50.00
Gross Labour Cost (S\$)			2,620.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >