

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: INDIA	DATE	: 22-Dec-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: GBG2911Y	KDH 2010159523	
MODEL	: TOYOTA HIACE	Jasper	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 22-Dec-20
		TIME	: 11:45HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SLIDING DOOR LH <i>Dented</i>	1	\$ 1,855.60	\$ 1,855.60
2	REAR FENDER LH <i>Reps</i>	1	\$ 2,355.90	\$ 2,355.90
3	REAR BUMPER <i>torn</i>	1	\$ 680.00	\$ 680.00
4	REAR BUMPER SIDE RETAINER <i>LH New</i>	2	\$ 62.40	\$ 124.80
			TOTAL PRICE	\$ 5,016.30
			LESS 25%	\$ 1,254.08
			SUB TOTAL PRICE	\$ 3,762.23

2258
1693.50

✓ 1655
x
568
62.40 x 2 = 124.80

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00
2	RIM COVER <i>lt</i>	1	\$ 240.00	\$ 240.00

✓
80

100

TOTAL \$ 260.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING AND REPLACE PARTS	\$ 1,200.00	<i>500</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>500</i>	

3	TRANSFER SLIDING DOOR MECHAISM	\$ 140.00	60	
4	TO REMOVE AND REFIX REVERSE SENSOR	\$ 80.00	50	

1110

TOTAL

\$2,620.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,762.23
TOTAL LABOUR COST : \$ 2,620.00
TOTAL REPAIR COST : \$ 6,382.23

Adrian L
L/S 22/12/20.
04 Days

APPROVED DETAILS

SURVEYOR : NTUC-MR CHEE SET CHAW

CONTACT NO :

FAX :

PART BY PART / LUMP SUM : \$ 1,791.70 (PART BY PART)

NO OF DAYS : 2 DAYS

total: 2903.50
L/S: 2.31K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: