



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2104047

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/06/2021
Reference CC3/CTI20014669/T1ra3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 1619J
Insured Veh. GBB 6726R
Claim No. SNM20D205110
Policy No. DMCVSNA00095622000
Accident Date 22/12/2020
Inspection Date 22/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI20014669/T1ra3q2	
			Date: 10/06/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 6726R		Veh. Inspected	SHA 1619J
Policy No.	DMCVSNA00095622000		Coverage (\$)	0.00
Claim No.	SNM20D205110		Excess (\$)	0.00
Assign From			Assign Date	22/12/2020
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40		c.c	1685
Engine No.	HIDDEN		Year of Reg.	2016
Chassis No.	KMHLB41UMHU095299		Colour	BLUE
Odometer	520255 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		205/60 R16	DURATURN	6 mm
L/H Front Tyre		205/60 R16	DURATURN	6 mm
R/H Rear Tyre		205/60 R16	DURATURN	6 mm
L/H Rear Tyre		205/60 R16	DURATURN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	22/12/2020		Inspection Date	22/12/2020
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1619J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER W LIP & FOG	DEFORMED	1,052.20	1,052.20
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	PANEL -FENDER LH	BENT	663.00	663.00
1	LAMP ASSY HEAD -LH	CUT	1,800.00	1,800.00
1	PANEL ASSY -FR DR LH	TO REPAIR SEE LABOUR	2,256.40	-
1	MIRROR ASSY O/S REA	CRACKED	670.00	670.00
1	PANEL ASSY RR DR LH	TO REPAIR SEE LABOUR	2,201.10	-
1	MOULDING ASSY -SIDE	TO REPAIR SEE LABOUR	732.80	-
1	COVER ASSY -RR BUMPE	TO REPAIR SEE LABOUR	1,106.00	-
1	CAP ASSY WHEEL HUB	CUT	217.20	217.20
1	CAP ASSY -WHEEL HUB	CUT	217.20	217.20
1	CAP ASSY WHEEL HUB	CUT	217.20	217.20
	LESS 20% DISCOUNT		-2,231.02	-971.76
			8,924.08	3,887.04
	<u>SPECIAL NETT ITEMS</u>			
1	(I40) FRT DOOR LOGO CTPL (SN)	NECESSARY	75.00	75.00
1	APP LOGO REAR DOOR L/R CT (SN)	NECESSARY	80.00	80.00
1	PROTECTOR MAT (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	FRT FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
1	FRT DOOR ADVERTISEMENT LOGO LH (SN)	CUT	100.00	100.00
1	REAR DOOR ADVERTISEMENT LOGO LH (SN)	CUT	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO LH (SN)	CUT	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
			755.00	705.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING (REPAIR RR FENDER LH).INCLUSIVE OF THE REPAIR OF PANEL ASSY -FR DR LH,PANEL ASSY RR DR LH ,MOULDING ASSY -SIDE AND COVER ASSY - RR BUMPE.		1,400.00	840.00
	SPRAYPAINT ON AFFECTED AREA.		1,250.00	1,200.00
	CHECK ALL LIGHTING .		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
	TRANSFER OF DOOR FRT LH .	NOT NECESSARY	120.00	-
	TRANSFER OF DOOR REAR LH .	NOT NECESSARY	120.00	-
	REMOVE/REFIX REVERSE SENSOR .		80.00	30.00
	ADJUST FRONT WHEEL ALIGNMENT .		120.00	80.00
			3,190.00	2,210.00
	GRAND TOTAL		12,869.08	6,802.04
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,450.00

Report Ref No. CC3/CTI20014669/T1ra3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 1619J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 1619J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

