

Our Job Ref No : 305440398
Date : 31.12.20

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr TAUFIKH
Vehicle Reg No. : SHA1619J CTPL

Fax :

22.12.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- GBB6726R
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$5,450.00
Final Lumpsum Repair cost \$5,450.00


3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : 
Name : Taufikh
Date : 12/1/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305440398
REGN NO : SHA1619J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 13.10.2016
DATE/TIME IN : 22.12.2020 12:20
ACCIDENT DATE : 22.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	1,052.20	20.00	841.76	de ✓
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	net ✓
0003	04-01-0103-0574-A	I40VC PANEL-FENDER LH+	1	663.00	20.00	530.40	bt ✓
0004	04-01-0103-0781-A	I40VC LAMP ASSY-HEAD LH#	1 L	1,800.00	20.00	1,440.00	end ✓
0005	04-01-0103-0593-G	I40VC PANEL ASSY-FR DR LH	1	2,256.40	20.00	1,805.12	Rx ✓
0006	04-01-0103-0600-G	I40VC MIRROR ASSY-O/S REA	1	670.00	20.00	536.00	ana ✓
0007	28-01-0103-0003-A	(I40)FRT DOOR LOGO CTPL	1 N	75.00	2.00-	75.00	na ✓
0008	04-01-0103-0596-G	I40VC PANEL ASSY-RR DR LH	1	2,201.10	20.00	1,760.88	Rx ✓
0009	28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	2.00-	80.00	net ✓
0010	04-01-0103-0813-G	I40VC MOULDING ASSY-SIDE	1	732.80	20.00	586.24	Rx ✓
0011	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00	20.00	884.80	Rx ✓
0012	04-01-0103-1150-A	I40VC PROTECTOR MAT	1	50.00	2.00-	50.00	✗ NN
0013	04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	217.20	20.00	173.76	cut ✓

4,858.80
-20%

3,887.04

+Nett 155

4,042.04

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305440398
 REGN NO : SHA1619J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 13.10.2016
 DATE/TIME IN : 22.12.2020 12:2
 ACCIDENT DATE : 22.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	217.20	20.00	173.76	ent-
0015 04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	217.20	20.00	173.76	ent-

SUB-TOTAL : 9,129.08

4,042.04

JOB NATURE

0000 20-05	REAR BUMPER ADVERTISMENT LOGO		50.00			rec-
0001 20-05	FRT FENDER ADVERTISMENT LOGO LH		100.00			rec-
0002 20-05	FRT DOOR ADVERTISMENT LOGO LH		100.00			ent-
0003 20-05	REAR DOOR ADVERTISMENT LOGO LH		100.00			ent-
0004 20-05	REAR FENDER ADVERTISMENT LOGO LH		100.00			ent-
0005 20-05	REAR FENDER ADVERTISMENT LOGO RH		100.00			rec-
0006 L	PANEL BEATING (repair rr fender Lh)	1400.00	840			

1400.00

840

550
 2,210
 2,760
 6,802.04
 - 202
 5,441.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305440398
 REGN NO : SHA1619J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 13.10.2016
 DATE/TIME IN : 22.12.2020 12:00
 ACCIDENT DATE : 22.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0007 23-502	SPRAYPAINT ON AFFECTED AREA	1250.00	1200.
0008 17-01	CHECK ALL LIGHTING	50.00	30.
0009 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	30.
0010 20-02	TRANSFER OF DOOR FRT LH	120.00	X NN
0011 20-02	TRANSFER OF DOOR REAR LH	120.00	X NN
0012 20-22	REMOVE/REFIX REVERSE SENSOR	80.00	30.
0013 20-08	ADJUST FRONT WHEEL ALIGNMENT	120.00	80.
		SUB-TOTAL	: 3,740.00

TOTAL : 12,869.08

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE

DATE :

Tanfer 97495749
 WP 22/12/20 @ 5pm
 e/s rising after repair
 fuptr @ hantol.com
 4-5 days

Durafurn
 6802.04
 L/S\$5450
 4DAYS
 \$5,450/-