

# REPAIR ESTIMATE\*

VEHICLE NO **SHC2912B** SHC29195

MAKE :

DATE 21.12.20

MODEL : IONIQ G2

CHIANG/ CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT RH DOOR PANEL			\$1,797.20
1	FRONT RH FENDER			\$588.80
1	FRONT RH BLUE DRIVE			\$26.60
1	FRONT BUMPER COVER			\$430.90
1	REAR WING MIRROR RH			\$1,391.70
1	FRONT DOOR OUTER HANDLE RH			\$234.80
1	FRONT DOOR OUTER MOULDING RH			\$110.10
1	WHEEL CAP RH			\$346.40
	<b>SUB TOTAL</b>			<b>\$4,926.50</b>
	<b>LESS 20%</b>			<b>\$985.30</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$3,941.20</b>
1	FRONT DOOR COMFORT LOGO STICKER			\$75.00
	<b>Labour Charge</b>			<b>\$75.00</b>
	Panel Beating			
	Spray Painting Charge			\$650.00
	Remove/refix door parts			\$700.00
	Check Wiring			\$120.00
	<b>TOTAL LABOUR</b>			<b>\$60.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$1,530.00</b>
				<b>\$5,546.20</b>

Handwritten notes in table:  
 3730  
 20% 248.40  
 75  
 373.40  
 920  
 \$1293.40  
 02 days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Toufah 17495749  
 WP' 22/12/20  
 02 days  
 p/g Resurvey after repair  
 Toufah @ lkhant.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: