

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-09 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

29/12/2020

Owner: NOOR AZIMAH BINTE MOM NAINA

ESTIMATE TO REPAIR HONDA VEZEL - SLQ4119J

1pc	front RH headlamp
1pc	front RH headlamp lower bracket
1pc	front bumper 815
1pc	front bumper reinforcement
20pcs	front bumper clip @\$5.00
1pc	front bumper grille
1pc	front bumper lower lid
1pc	front bumper lower rubber
1pc	front bumper lower cover
1pc	front bumper RH side retainer
1pc	front bumper RH fog lamp 309.30
1pc	front bumper RH fog lamp base
1pc	front bumper RH fog lamp garnish 52.30
1pc	front centre grille base
1pc	front wiper tank
1pc	front RH fender
1pc	front RH fender protector
1pc	front RH fender inner shield
8pcs	front RH fender inner shield clip @\$5.00

mgcm	\$ 1,759.40	✓
cm	\$ 45.00	✓
B	\$ 927.50	✓
B	\$ 285.20	✓
he	\$ 100.00	5012
nd	\$ 195.20	✓
Bu	\$ 485.50	✓
D11	\$ 185.50	—
su	\$ 325.50	X
cm	\$ 38.10	✓
cm	\$ 385.50	✓
nd	\$ 85.50	✓
D11	\$ 125.50	✓
su	\$ 480.50	X
su	\$ 280.50	X
R	\$ 580.00	X
Bu	\$ 195.00	✓
D11	\$ 195.25	✓
na	\$ 40.00	✓

\$ 6,714.65

\$ 1,342.93

\$ 5,371.72

less 20%

wiring
tuffkote
spray painting
labour charges
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

\$	80.00	201
na	\$ 60.00	X 4401
\$	1,000.00	4601
\$	1,000.00	
\$	7,511.72	



AIC
veh in
30/12/20
LKK
Kenneth
Not Authorised
C1 Imp @ 3650k
Resurvey After Paint
3 days