



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

28/12/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 28/12/2020

Estimated repair cost for vehicle no: SJP8311Y HYUNDAI ELANTRA GLS 1.6 A '18

CHASSIS: KMHD841CMJU687975

TPAXA.

Ccilia.

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Repis</i>		\$1,358.00	+
2	2	Rear Boot Lid Hinge <i>Nre m</i>	\$84.30	\$168.60	+
3	1	Rear Boot Lid Emblem Logo <i>for</i>		\$28.80	✓
4	1	Rear Boot Lid Elantra Logo		\$38.50	✓
5	1	Rear Boot Lid Lock <i>Nre m</i>		\$116.20	+
6	1	Rear Boot Lid Weatherstrip <i>for</i>		\$80.60	✓
7	2	Rear Tail Lamp Lower Bracket <i>for</i>	\$28.00	\$56.00	+
8	1	Rear Bumper <i>Delud</i>		\$489.00	✓
9	10	Rear Bumper Clip <i>an</i>	\$6.50	\$65.00	30
10	2	Rear Bumper Side Retainer <i>Nre m</i>	\$40.00	\$80.00	+
11	2	Rear Bumper Side Reflector <i>an</i>	\$58.00	\$116.00	✓
12	1	Rear Bumper Lower <i>Delud</i>		\$242.80	✓
13	1	Rear Bumper Lower Cover <i>for</i>		\$135.50	✓
14	1	Rear Bumper Reinforcement <i>Best</i>		\$328.00	✓
15	2	Rear Bumper Reinforcement Bracket <i>for</i>	\$34.00	\$68.00	+
16	5	Rear Bumper Top & Lower Bracket <i>for</i>	\$36.00	\$180.00	+
17	1	Rear Bumper Reverse Sensor (Special Nett) <i>and</i>		\$380.00	2000
18	1	Rear End Panel <i>Repis</i>		\$379.00	+
19	1	Rear End Panel Top Garnish <i>Nre m</i>		\$105.00	+
20	1	Rear Spare Tyre Panel Top Cover <i>for</i>		\$225.00	+
21	1	Rear Spare Tyre Panel & End Panel Sealant <i>for</i>		\$450.00	+

Subtotal :- \$5,090.00

140860

112688 S.N = 200

Labour charges

To remove & refit cushion & trim board

~~\$280.00~~ 40

Rear Bumper ceramic coating

~~\$400.00~~ 200

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit reverse camera

~~\$180.00~~ X

To check wiring

~~\$100.00~~ 30

Tuff kote

1360

~~\$150.00~~ 40

Panel beating

100

~~\$1,200.00~~ 400

Spray painting

100

~~\$1,200.00~~ 600

Subtotal :- \$3,610.00

Total:- \$8,700.00

Adrian Lj

P/P 29/12/20-

03 Days.

total: 2686.88

(P/P)

2686.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____