

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2012-196

DATE : 24-Dec-2020

POLICY NO. : FWD PNPV2018-00015401-01

VEHICLE REG. NO. : SLV4052R

VEHICLE MAKE : HONDA VEZEL 1.5X CVT

TO Motor Claim Department**AXA INSURANCE SINGAPORE PTE LTD**

8 Shenton Way, #27-01 AXA Tower, Singapore 068811

Tel: 1800-880-4741

Fax: 6880 4740

FOR SURVEYOR**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper	1	\$ 880.00	\$ 880.00
2	Front Bumper Clips	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer RH	1	\$ 30.00	\$ 30.00
4	Front Bumper Retainer LH	1	\$ 30.00	\$ 30.00
5	Front Reinforcement	1	\$ 380.00	\$ 380.00
6	Rear Bumper	1	\$ 880.00	\$ 880.00
7	Rear Bumper Clip	10	\$ 5.00	\$ 50.00
8	Rear Bumper Retainer RH	1	\$ 30.00	\$ 30.00
9	Rear Bumper Retainer LH	1	\$ 30.00	\$ 30.00
10	Rear Undercover Cover	1	\$ 280.00	\$ 280.00
11	Rear Tailgate Door	1	\$ 1,080.00	\$ 1,080.00
12	Rear Tailgate Door Lock	1	\$ 280.00	\$ 280.00
13	Rear Tailgate Door Lock Latch	1	\$ 50.00	\$ 50.00
14	Rear Tailgate Door Rubber Seal	1	\$ 120.00	\$ 120.00
15	Rear Vezel Emblem	1	\$ 80.00	\$ 80.00
16	Rear Honda Emblem	1	\$ 80.00	\$ 80.00
17	Rear / End Panel Garnish	1	\$ 200.00	\$ 200.00
18	End Panel	1	\$ 480.00	\$ 480.00
19	Rear Windscreen Molding	1	\$ 100.00	\$ 100.00
Total Spare Parts				\$ 5,110.00
	<u>SPECIAL NETT</u>			
20	Front License Plate with Frame	1	\$ 40.00	\$ 40.00
21	Rear Windscreen Sealant	1	\$ 40.00	\$ 40.00
22	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 280.00
	<u>LABOUR</u>			
23	Spray Painting Front Bumper and Whole Rear include Blending	1	\$ 1,000.00	\$ 1,000.00
24	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 1,200.00	\$ 1,200.00
25	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
26	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00
27	Remove and Refit Rear Windscreen	1	\$ 120.00	\$ 120.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2012-196

DATE : 24-Dec-2020

POLICY NO. : FWD PNPV2018-00015401-01

VEHICLE REG. NO. : SLV4052R

VEHICLE MAKE : HONDA VEZEL 1.5X CVT

TO Motor Claim Department

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way, #27-01 AXA Tower, Singapore 068811

Tel: 1800-880-4741

Fax: 6880 4740

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
28	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
29	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour \$ 2,610.00**Amount Before Excess** \$ 8,000.00**Add GST @ 7%** 560.00**Total Amount Payable** \$ 8,560.00