



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2012-196
DATE : 24-Dec-2020
POLICY NO. : FWD PNPV2018-00015401-01
VEHICLE REG. NO. : SLV4052R
VEHICLE MAKE : HONDA VEZEL 1.5X CVT

TO Motor Claim Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Tel: 1800-880-4741
Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper <i>X R</i>	1	\$ 880.00	\$ 880.00 <i>X</i>
2	Front Bumper Clips <i>X SVC</i>	10	\$ 5.00	\$ 50.00 <i>X</i>
3	Front Bumper Retainer RH <i>X SVC</i>	1	\$ 30.00	\$ 30.00 <i>X</i>
4	Front Bumper Retainer LH <i>X SVC</i>	1	\$ 30.00	\$ 30.00 <i>X</i>
5	Front Reinforcement <i>? X SVC</i>	1	\$ 380.00	\$ 380.00 <i>X</i>
6	Rear Bumper <i>/ CRU</i>	1	\$ 880.00	\$ 880.00 <i>/</i>
7	Rear Bumper Clip <i>/ NRC</i>	10	\$ 5.00	\$ 50.00 <i>/</i>
8	Rear Bumper Retainer RH <i>X SVC</i>	1	\$ 30.00	\$ 30.00 <i>X</i>
9	Rear Bumper Retainer LH <i>X SVC</i>	1	\$ 30.00	\$ 30.00 <i>X</i>
10	Rear Undercover Cover <i>X SVC</i>	1	\$ 280.00	\$ 280.00 <i>X</i>
11	Rear Tailgate Door <i>/ BD</i>	1	\$ 1,080.00	\$ 1,080.00 <i>/</i>
12	Rear Tailgate Door Lock <i>/ Jan</i>	1	\$ 280.00	\$ 280.00 <i>/</i>
13	Rear Tailgate Door Lock Latch <i>X SVC</i>	1	\$ 50.00	\$ 50.00 <i>X</i>
14	Rear Tailgate Door Rubber Seal <i>X SVC</i>	1	\$ 120.00	\$ 120.00 <i>X</i>
15	Rear Vezel Emblem <i>/ NRC</i>	1	\$ 80.00	\$ 80.00 <i>/</i>
16	Rear Honda Emblem <i>X SVC</i>	1	\$ 80.00	\$ 80.00 <i>X</i>
17	Rear / End Panel Garnish <i>X SVC</i>	1	\$ 200.00	\$ 200.00 <i>X</i>
18	End Panel <i>X R</i>	1	\$ 480.00	\$ 480.00 <i>X</i>
19	Rear Windscreen Molding <i>/ NRC</i>	1	\$ 100.00	\$ 100.00 <i>/</i>
Total Spare Parts				\$ 5,110.00 <i>2,470</i>
SPECIAL NETT				
20	Front License Plate with Frame <i>X SVC</i>	1	\$ 40.00	\$ 40.00 <i>X</i>
21	Rear Windscreen Sealant <i>/ MRC</i>	1	\$ 40.00	\$ 40.00 <i>/</i>
22	Reverse Sensor <i>/ show</i>	1	\$ 200.00	\$ 200.00 <i>/</i>
Total Special Nett				\$ 280.00 <i>240</i>
LABOUR				
23	Spray Painting Front Bumper and Whole Rear include Blending	1	\$ 1,000.00	\$ 1,000.00 <i>600</i>
24	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 1,200.00	\$ 1,200.00 <i>600</i>
25	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00 <i>30</i>
26	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00 <i>50</i>
27	Remove and Refit Rear Windscreen	1	\$ 120.00	\$ 120.00 <i>/</i>



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2012-196
DATE : 24-Dec-2020
POLICY NO. : FWD PNPV2018-00015401-01
VEHICLE REG. NO. : SLV4052R
VEHICLE MAKE : HONDA VEZEL 1.5X CVT

TO Motor Claim Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Tel: 1800-880-4741
Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
28	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
29	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,610.00
Amount Before Excess				\$ 8,000.00
Add GST @ 7%				560.00
Total Amount Payable				\$ 8,560.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

Repair day - 4 days

~~415~~ PIP
before
~~After~~ paint photo

Sun Pm (LH)

28/12/2020

TP without prejudice

2,470
- 20%
1,976
240
1,470
3,686

PIP
\$3,686
4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: