



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 28.12.2020
Emailed : 20.01.2021, 9.30am
Date Survey : 29.12.2020

VEHICLE NO : SLZ 1928 M
MODEL : MIT ATTRAGE 1.2
WIP : 61278

Material	:	\$	1,166.55
Labour	:	\$	3,520.00
Sub-Total	:	\$	4,686.55
REPAIR LIMIT	:	\$	-
Less Excess	:	\$	-
Total	:	\$	4,686.55
GST 7%	:	\$	328.06
Grand Total	:	\$	5,014.61
Finalise By/Date	:	LOI / 20/01/2021	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim

☐ Claim GIA / LTA fee

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 13/01/2021	Cust No/Name	/Lee Heok Yong
	Reg No/Reg Date	SLZ1928M / 26/04/2018
	Date In/Mileage	13/01/2021/ 44313
	Chassis/Package	MMBSTA13AJH001855 /DC17S3C
	Engine No	3A92UGS5536
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	19/01/2021/ 18:04	TLD	260 / AiTing	61278			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE RH REAR DOOR, REPAIR REAR BUMPER, REAR BODY KITS, RH REAR FENDER, RH SIDE SKIRTING, RH FRONT DOOR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 900.00
E PNT88000 TRANSFER RH REAR DOOR TRIM, DOOR GLASS, MECHANISMS, AND ALL OTHER ATTACHMENTS TO NEW DOOR PANEL								✓ 120.00
E PNT98000 RESPRAY ON RH REAR DOOR, REAR BUMPER, REAR BODY KITS, RH REAR FENDER, RH SIDE SKIRTING, RH FRONT DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 2100.00
M SUNDRY APPLY BODY SEALANT ON AFFECTED								✓ 40.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								✓ 30.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								✓ 40.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT								✓ 120.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB TRANSFER RH REAR SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING								✓ 30.00
X	PANEL ASSY,RR DOOR,RH				1.00	✓ 799.00	23.00	615.23
X	TAPE,RR DOOR SASH,RH				1.00	✓ 29.00	23.00	22.33
X	WHEEL,DISC				1.00	✓ 687.00	23.00	528.99
Z TEXT TP CLAIM AIG SKX497T DOA : 28.12.20								

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 13/01/2021	Cust No/Name	/Lee Heok Yong
	Reg No/Reg Date	SLZ1928M / 26/04/2018
	Date In/Mileage	13/01/2021/ 44313
	Chassis/Package	MMBSTA13AJH001855 /DC17S3C
	Engine No	3A92UGS5536
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/01/2021/ 18:04	TLD	260 / AiTing	61278

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
SURVEYOR STEVE (LKK) 29.12.20 REPAIR 05 DAYS				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	1,166.55	Nett	4,686.55
Labour	3,390.00	7% GST on	4686.55
Standard Menu	0.00		
Specialist Job	30.00	Total Payable	5,014.61
Diagnostics Job	0.00		
Sundry/Others	100.00		
Total(w/o GST)	4,686.55		

This is not an official tax invoice.
This is a computer generated document, no signature is required.

Work Order: R001314
License: SLZ1928M
Technician: ALVIN (108)
Mileage: 44313
Date: 18.1.21 18:59

Mitsubishi : Mirage/Attrage : 2012- (Including G4)

Front : Left

Actual	Before	Specified Range
-0°25'	-0°23'	-0°40' 0°50'
3°52'	3°46'	3°15' 4°45'
0°02'	-0°09'*	-0°07' 0°07'
12°21'	12°19'	10°05' 13°05'
11°56'	11°56'	9°25' 13°55'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°34'	-0°34'	-0°40' 0°50'
4°27'	4°28'	3°15' 4°45'
0°01'	-0°02'	-0°07' 0°07'
12°11'	12°08'	10°05' 13°05'
11°38'	11°34'	9°25' 13°55'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°08'	0°11'	-0°30' 0°30'
-0°34'*	-0°42'*	-0°30' 0°30'
0°10'	0°11'	
0°03'	-0°12'	-0°14' 0°14'

Rear : Left

Actual	Before	Specified Range
-0°59'	-0°59'	-1°45' -0°15'
0°12'	0°12'	-0°01' 0°13'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°11'	-1°11'	-1°45' -0°15'
0°05'	0°04'	-0°01' 0°13'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°11'	0°12'	-0°30' 0°30'
0°17'	0°17'	-0°02' 0°26'
0°04'	0°04'	

SLZ1928M

After Repair to Car out Diagnostic check on electronic control system
to check all the sensors
to be done.

2021.01.18

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	A13A 2018MY

2021.01.18