



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model Colour/Trim	/Lee Heok Yong SLZ1928M / 26/04/201 / 0 MMBSTA13AJH001855 3A92UGS5536 MIT/18MY ATTRAGE 1.2 CVT W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	29/12/2020/ 12:49	QUD	247 / DonBong	61278		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON RH REAR DOOR, REPAIR REAR BUMPER, REAR BODY KITS, REPAIR RH REAR FENDER, REPAIR RH SIDE SKIRTING, REPAIR RH FRONT DOOR,				2 x 450			1800.00
E PNT88000 TRANSFER RH REAR DOOR TRIM, DOOR GLASS, MECHANISM AND OTHERS ATTACHMENT TO NEW DOOR PANEL							120.00
E PNT98000 PAINT WORK SPRAY RH REAR DOOR, REAR BUMPER, REAR BODY KITS, RH REAR FENDER, RH SIDE SKIRTING, RH FRONT DOOR AND AFFECTED PORTION				350 x 6			2450.00
M SUNDRY APPLY BODY SEALANT							80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							30.00
M SUNDRY PERFORM RUST PREVENTION							80.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment							120.00
M SUNDRY LABOUR RENEW RH REAR SPORT RIM INCLUDING BALANCING							30.00
M SUNDRY SUNDRIES							50.00
M PANEL ASSY, RR DOOR, RH				1.00	799.00	23.00	615.23
M TAPE, RR DOOR SASH, RH				1.00	29.00	23.00	22.33
M BRACKET, RR BUMPER, LH				1.00	28.00	23.00	21.56
M BRACKET, RR BUMPER, RH				1.00	28.00	23.00	21.56
M CLIP, RR BUMPER				10.00	4.00	23.00	30.80
M WHEEL, DISC				1.00	687.00	23.00	528.99

Estimate

STEVE CLKK

WHL

Surveyor Signature:

Estimate

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: WHT

Confirm & accepted by

DATE: 29/12/20, 1:30 pm

REMARKS: 5 days

7% GST on

Nett
6120.47

6,120.47
428.43

Total Payable

6,548.90

- L&K Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party insurance claim
- No illegal modification or tampering
- Supplier is S

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.