

ASSIGNMENT

From: Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: GK3-3419536

at Workshop m/s New hock Tech

of

Insured: XD 2745R

Policy No.

Claims No. CMTD2003813/nye

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 1.7% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GK3-3419536 Yr Regn: new car

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: Monde Ritz c.c. 1317

Colour: white A/C: Insured / Std / NI / NA

Sp. Read: 000017 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GK3 341.9536

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / PS/Rim / STD A/Rim or

Tyre Size: F: 175/70 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 23/12/20

Survey held at

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 30/12/20

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Towing Bill

6/1/21 PIP \$2948.16 confirmed with MR Chew (Red \$2958.44, 50%)
 07/01/21 @ 12.40pm referred to Melvin Ye by email.

Date/Time, File Pass to?

1) 07/01/21 ☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 2

Report Format : TP

Lump Sum / I.B.I. (\$) 2948.16

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Platinum Group Pte Ltd

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 23/12/2020

Estimated repair cost for vehicle no: HONDA FIT 1.3A G-F

CHASSIS: GK3-3419536

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid	845.00	\$955.00
2	1	Rear Boot Lid Honda Logo		\$85.00
3	1	Rear Boot Lid Fit Logo		\$45.00
4	1	Rear Bumper	492.70	\$790.80
5	1	Rear Bumper Clip	35.00	\$52.00
6	1	Rear Bumper Reverse Sensor		\$380.00
7	2	Rear Bumper Side Retainer	17.30	\$170.00
8	1	Rear R/H Tail Lamp	325.00	\$527.40
9	1	Rear End Panel		\$390.60
10	1	Rear End Panel Top Garnish		\$90.80

202

Subtotal :- \$3,486.60

Labour charges

To remove & refit trimboard 60 \$180.00

To remove & refit reverse sensor 50 \$100.00

To remove & refit rear windscreen 120 \$120.00

gum Rear windscreen sealant 40 SN \$50.00

To check wiring 20 \$100.00

Tuff kote 30 \$150.00

Not Afford

29/12/2020

p/p \$ 2948.16

Take the Bedu party.
including parts

3 days

Towing

100 \$120.00

Panel beating

520 \$800.00

Spray painting

600 \$800.00

Subtotal :- \$2,420.00

Total:- \$5,906.60

LKS Auto Consultant is hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-1760.20

20%

1408.16

1840

2948.16

CASH SALE / WORK ORDER



顺辉拖车服务

SOON HWEE TOWING SERVICE

Blk 9002 Tampines St 92 #01-74 Singapore 528836

Handphone : 9720 3785

24 HOURS TOWING SERVICES

No: 8393

Date: 29/12/2020

宝号

Messrs: N. H. T

车号

Vehicle No: NIL

Model No: 4/Fit

由

From: Premier #03-36

到

To: Auto Bay

时间(日/夜)

Time (Day / Night):

☐ Accident

☐ Jump Start

☐ King Tow

☐ Hoist

☐ Others:

CASH \$: 501

CHEQUE:

注意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一切由车主自行负责。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdeemeanour to your vehicle whilst being towed.

经手人

Authorised by:

收货人

Received by:

CASH SALE / WORK ORDER



顺辉拖车服务

SOON HWEE TOWING SERVICE

Blk 9002 Tampines St 92 #01-74 Singapore 528836

Handphone : 9720 3785

24 HOURS TOWING SERVICES

No: 8399

Date: 2/1/2024

宝号

Messrs: N.H.T #01-43

车号

Vehicle No: NIL

由

From: Auto Bay

时间(日/夜)

Time (Day / Night):

Model No: H/Fit

到

To: Premier #03-36

☐ Accident

☐ Jump Start

☐ King Tow

☐ Hoist

☐ Others:

CASH \$: 50h

CHEQUE:

注意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一切由车主自行负责。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdeemeanour to your vehicle whilst being towed.

经手人

Authorised by:

收货人

Received by:



To:
PLATINUM GROUP PTE LTD
8 KAKI BUKIT AVENUE 4
#03-36 PREMIER @ KAKI BUKIT
SINGAPORE 415875

DATE: 21/11/2020

Official Receipt

We , **Hyperformance Pte Ltd**, have sold and received full payment from **PLATINUM GROUP PTE LTD** for the vehicles bearing the chassis number /engine as mentioned below :

Make & Model : HONDA FIT 1.3 G-F

Chassis No.	Engine No.
GK3-3419536	L13B-3934026

Your Sincerely ,



Name: Ng Chung Wai
Designation: Director