

Estimation

Date _____
 Vehicle SJV 9493 S
 Make/Model BMW 520I
 Chassis No. WBA5A32010D335162

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	HEADLAMP RH	1	\$	\$ cut 4224.75
2	HEADLAMP BALLAST RH	1		\$ X nn 893.90
3	HEADLAMP LOWER BRACKET RH	1	\$ 321.00	\$ 6 ✓ cra 321.00
4	HEADLAMP NOZZLE RH	1	\$ 309.00	\$ X nn 309.00
5	FRONT BUMPER	1	\$ 1,621.40	\$ de ✓ 1,621.40
6	FRONT BUMPER LOGO - BMW	1	\$ 110.00	\$ rel ✓ 110.00
7	FRONT BUMPER GRILLE L+R	2	\$ 135.15	X \$ 270.30 nn
8	FRONT BUMPER GRILLE CHROME FRAME L+R	2		X
9	FRONT BUMPER GRILLE INNER BRACKET L+R	1		X \$ 86.90 nn
10	FRONT BUMPER GRILLE FAN	1		X \$ 401.75 nn
11	FRONT BUMPER GRILLE FAN MOTOR	1		X
12	FRONT BUMPER NOZZLE COVER RH	1	\$ 85.00	\$ X nn 85.00
13	FRONT BUMPER NOZZLE COVER LEVER RH	1	\$ 162.00	\$ X nn 162.00
14	FRONT BUMPER LOWER GRILLE	1	\$ 374.00	\$ X nn 374.00
15	FRONT BUMPER TOW COVER RH	1	\$ 374.00	\$ X nn 374.00
16	FRONT BUMPER FOGLAMP RH	1	\$ 311.00	\$ cut ✓ 311.00
17	FRONT BUMPER FOGLAMP GRILL RH	1	\$ 179.00	\$ cut ✓ 179.00
18	FRONT BUMPER FOGLAMP GRILL GARNISH RH	1	\$ 186.00	\$ cut ✓ 186.00
19	FRONT BUMPER SENSOR SET	1	\$ 265.00	\$ and ✓ 1,060.00
20	FRONT BUMPER RETAINER RH	1	\$ 101.00	\$ ✓ cra 101.00
21	FRONT BUMPER REINFORCEMENT BAR	1	\$ 795.00	\$ X nn 795.00
22	FRONT BUMPER SPONGE	1	\$ 170.00	\$ ✓ cut 170.00
23	FRONT BUMPER UNDERCOVER	1	\$ 249.00	\$ X nn 249.00
24	FRONT FENDER RH	1	\$ 974.00	\$ bf ✓ 974.00
25	FRONT FENDER COWLING RH	1	\$ 181.00	\$ ✓ cut 181.00
26	FRONT SUPPORT PANEL	1	\$ 634.00	\$ X nn 634.00
27	FRONT SUPPORT PANEL TOP GARNISH	1	\$ 203.00	\$ X nn 203.00
			Less 5%	14,127.7
			Total	\$ 12,567.15 10,395.85

	S/Nett Items			
1	FRONT BUMPER CLIPS	10	\$ 10.00	\$ 30 AP ✓ 100.00
2	FRONT FENDER COWLING CLIPS	10	\$ 10.00	\$ 20 ✓ nec 100.00
3	FRONT SUPPORT PANEL TOP GARNISH CLIPS	10	\$ 10.00	\$ X nn 100.00
			Total	\$ 300.00

	LABOUR				
1	SPRAY PAINT ON AFFECTED AREAS	1	1250	\$ 500 500	1,250.00
2	PANEL BEATING ON AFFECTED AREAS	1	800	\$ 500 500	800.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	1	150	\$ 700 150	150.00
4	TO CHECK WIRING AND FOG LAMP FUNCTION	1	150	\$ 50 50	150.00
5	TO UNLOAD AND RNR UPHOISTERY	1	400	\$ X	400.00
6	TO CHECK WATER LEAK	1	150	\$ X	150.00
7	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	1200	\$ 150 150	1,200.00
8	TO PERFORM RUST PROOFING	1	400	\$ 30 30	400.00
9	TO RNR FRONT SENSOR AND CHECK FUNCTION	1	400	\$ 30 30	400.00
			Total	\$	4,900.00

Parts Replacement Amount \$ 10,695.85

Total Amount For Labour \$ 4,900.00

Total Amount \$ 15,595.85

18,763.15

Tanpin 97495744
 WP' 21/12/2023 pm
 US Resurvey after repair
 Tanpin C/handover
 Bv 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: