

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/1021/2020/NS
DATE : 29-Dec-20
WIP : 64441

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SMH 6945 S

CHINA TAIPING INSURANCE (SG) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

OWNER'S NAME : MR WONG ZHENG YANG, ERNEST
ADDRESS : BLK 453A BUKIT BATOK WEST AVENUE 6
#22-757
SINGAPORE 651453
TELEPHONE : HP +65 93394723
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070159166
VEHICLE NO : **SMW 3596 C**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 16/11/2020
ENGINE NO : CZD C06821
CHASSIS NO : WAUZZZF37M1014736
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Dec-20
PLACE OF ACCIDENT : PARKING LOT AT LEVEL 313 AT MULTI STOREY CARPARK
LEVEL 3B

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 3596 C

| S/N | NATURE OF JOBS | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--|----------------------|----------------------------|
| 1 | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FRO HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N \$ 480.00 | |
| 2 | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. | S/N \$ 400.00 | |
| 3 | TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 1,200.00 | |
| 4 | TO RESPRAY FRONT BUMPER. | \$ 1,000.00 | |
| 5 | TO CARRY OUT DIAGNOSTIC CHECK. | S/N \$ 192.00 | |
| TOTAL LABOUR CHARGES | | : \$ 3,272.00 | |

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 3596 C

| S/N PARTS DESCRIPTION | QTY | DAMAGED PARTS & PRICES | |
|---|----------|------------------------|---------|
| | | S/NETT | REMARKS |
| 1 FRONT BUMPER | | \$ 2,045.00 | |
| 2 FRONT BUMPER CLOSING ELEMENT - RH | | \$ 58.00 | |
| 3 FRONT BUMPER GRILLE - CENTRE | | \$ 215.00 | |
| 4 FRONT BUMPER CLOSING ELEMENT | | \$ 188.00 | |
| 5 FRONT BUMPER GRILLE - RH | | \$ 109.00 | |
| 6 FRONT SPOILER | | \$ 379.00 | |
| 7 FRONT BUMPER AIR GUIDE GRILLE - RH | | \$ 151.00 | |
| 8 FRONT BUMPER GUIDE SECTION - RH | | \$ 38.00 | |
| 9 HEADLIGHT MOUNTING - RH | | \$ 117.00 | |
| 10 LED HEADLIGHT - RH | | \$ 5,526.00 | |
| 11 LIFT CYLINDER - RH | | \$ 208.00 | |
| 12 FRONT WHEEL COVER - LH/RH | 2 | \$ 530.00 | |
| 13 WHEEL HOUSING LINER - RH FRONT | | \$ 237.00 | |
| 14 WHEEL HOUSING LINER ATTACHMENT PARTS | | \$ 100.00 | |
| 15 SUNDRIES | | \$ 200.00 | |
| TOTAL SPARE PARTS | : | \$ 10,101.00 | |
| TOTAL LABOUR CHARGES | : | \$ 3,272.00 | |
| GRAND TOTAL | : | \$ 13,373.00 | |

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT