

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 48992400W

TP China
Denise

3946.26
3157.

310

Amount :	\$	640.00
----------	----	--------

Labour	Amount (\$)	
To check rear electrical wiring system	\$ 40.00	30
To transfer rear boot component parts to new rear boot	\$ 120.00	80
To transfer rear windscreen to new rear boot	\$ 150.00	120
To remove, replace, and reinstall rear reverse sensors	\$ 40.00	✓
To apply anti-rusting coating on new and affected areas	\$ 70.00	60
To remove & reinstall rear interior trims, garnishes etc for necessary repair	\$ 120.00	60
To remove & reinstall exhaust	\$ 150.00	X
Labour to remove, cut, change & panel beating	\$ 1,000.00	800
To putty and respray affected areas	\$ 800.00	700
Labour Total :	\$ 2,490.00	
Total (Parts & Labour)	\$ 9,206.98	

Adrian Lj
H/S 30/12/20.
06 Days.

Total: 5357

H/S: 4.2K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: