


Low Tze Chiang  
Blk 892B Woodlands Drive 50  
#05-161  
Singapore 731892

*Not Notified*  
*11 Day @ 2500/-*  
*Primary After Pain*  
*5 day*



SH/2020/099/12/004/TP  
19-January-2021

Estimated cost of repair for vehicle no : **SJM4616K Toyota Camry**  
Accident involving vehicle no: **SJM4616K & SLV2734U** on **23.12.2020**

Description	Quantity	Cost Price
RH rear door	1	S <i>R</i> 1,248.00 ✓
RH rear door protector	1	S <i>M</i> 91.70 ✓
RH rear door inner lock	1	S <i>R</i> 529.10 X
RH rear bumper retainer	1	S <i>R</i> 79.40 X
RH rear wheel rim 16" <i>P: 858</i>	1	S <i>Real</i> 2,010.10 ✓
RH rear knuckle arm	1	S <i>R</i> 599.10 X
RH rear knuckle arm wheel bearing	1	S <i>W</i> 611.70 A
RH rear lower arm	1	S <i>R</i> 420.60 X
RH rear control arm	1	S <i>R</i> 590.60 X
RH rear thrust arm	1	S <i>R</i> 511.90 X
RH rear shock absorber	1	S <i>R</i> 429.50 X
		S 7,121.70
		S <b>Less 25%</b> 1,780.43
		S <b>5,341.28</b>
To remove and check RH rear suspension system and replace damaged parts		S <i>W</i> 240.00 X
To perform computerised wheel alignment		S 65.00 <i>601</i>
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality		S 15.00 ✓
To remove damaged parts, to jack out RH rear fender panel, to reweld, reshape and repair RH rear fender and inner panel, Rear bumper, RH runnign board garnish, to remove and refit RH rear door trim, lock, window and adjust body panel alignment		S 680.00 <i>600</i>
To spray paint affected RH rear and inner damaged portion inclusive of preparatory works and material		S 850.00 <i>800</i>
		<b>S 7,191.28</b>

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

T/Party: AIG Asia Pacific Insurance Pte Ltd