



Tax Invoice No.:	AR202103-0089
------------------	---------------

LOW TZE CHIANG
 BLK 892B #05-161
 WOODLANDS DRIVE 50
 SINGAPORE 731892

File No : SH/2020/099/12/004/TP
 Date : 26-March-2021

Cost of repair for vehicle no: SJM4616K TOYOTA CAMRY 2.0 AUTO
 Accident involving vehicle no: SJM4616K & SLV2734U on 23-December-2020

Description

To Supply Spare Parts

To perform computerised wheel alignment.

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality.

To remove damaged parts, to jack out RH rear fender panel, to reweld, reshape and repair RH rear fender and inner panel, rear bumper, RH running board garnish, to remove and refit RH rear door trim, lock, window and adjust body panel alignment.

To spray paint affected RH rear and inner damaged portion inclusive of preparatory works and material.

Lump Sum Cost of Repair \$	2,500.00
7% GST \$	175.00
\$	2,675.00

T/Party: AIG ASIA PACIFIC INSURANCE PTE LTD

Received By

No signature is required as this is a computer generated invoice