

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

24/12/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPA 16

Cecilwa

Accident date: 24/12/2020

Estimated repair cost for vehicle no: SJE4144Y HONDA FIT 1.3L AT 08

CHASSIS: GE61045743

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Dented</i>		\$820.30	✓
2	2	Rear Boot Lid Hinge <i>new</i>	\$48.90	\$97.80	+
3	2	Rear Boot Lid Shock Absorber <i>new</i>	\$184.90	\$369.80	+
4	1	Rear Boot Lid Emblem Logo <i>new</i>		\$38.10	✓
5	1	Rear Boot Lid Fit Logo <i>new</i>		\$38.00	+
6	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00	+
7	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$48.20	\$96.40	+
8	1	Rear Boot Lid Centre Moulding <i>new</i>		\$120.60	+
9	6	Rear Boot Lid Centre Moulding Clip <i>new</i>	\$6.50	\$39.00	+
10	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$232.10	✓
11	1	Rear Boot Lid Inner Rubber <i>new</i>		\$128.10	✓
12	1	Rear Boot Lid Inner Trim Board <i>cracked</i>		\$296.70	✓
13	1	Rear Boot Lid Wiper Link <i>new</i>		\$175.90	+
14	1	Rear Boot Lid Wiper Cover <i>new</i>		\$45.00	+
15	1	Rear Boot Lid Wiper Arm <i>new</i>		\$86.00	+
16	1	Rear Boot Lid Wiper Motor <i>new</i>		\$328.50	+
17	1	Rear Boot Lid Windscreen <i>new</i>		\$1,256.20	+
18	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$136.20	✓
19	2	Rear Tail Lamp <i>new</i>	\$296.50	\$593.00	✓
20	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00	✓
21	2	Rear Tail Lamp Panel <i>new</i>	\$191.70	\$383.40	+
22	2	Rear Tail Lamp Inner Panel <i>new</i>	\$482.30	\$964.60	+
23	1	Rear Bumper <i>Damaged</i>		\$494.60	✓
24	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00	30
25	2	Rear Bumper Side Retainer <i>new</i>	\$28.70	\$57.40	✓
26	1	Rear Bumper Towing Cover <i>Damaged</i>		\$28.00	✓
27	2	Rear Bumper Mud Shield <i>new</i>	\$94.80	\$189.60	+
28	8	Rear Bumper Mud Shield Clip <i>new</i>	\$6.50	\$52.00	+

29	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>	\$350.00	<i>200/sv</i>
30	1	Rear End Panel <i>Dishd</i>	\$365.30	✓
31	1	Rear End Panel Top Garnish <i>Delnd</i>	\$140.20	✓
32	2	Rear Fender <i>Regis</i>	\$682.20	\$1,364.40 <i>x</i>
33	2	Rear Fender Glass <i>Neu</i>	\$288.00	\$576.00 <i>x</i>
34	2	Rear Fender Air Duct <i>Neu</i>	\$38.00	\$76.00 <i>x</i>
35	2	Rear Fender Inner Panel <i>3 Regis</i>	\$633.00	\$1,266.00 <i>x</i>
36	2	Rear Fender Inner Housing	\$596.40	\$1,192.80 <i>x</i>
37	2	Rear Fender Top Trim Board <i>Neu</i>	\$293.60	\$587.20 <i>x</i>
38	2	Rear Fender Inner Trim Board <i>LH Delnd, RH cnd</i>	\$339.80	\$679.60 <i>570</i>
39	16	Rear Fender Inner Trim Board Clip <i>Neu</i>	\$6.50	\$104.00 <i>60</i>
40	1	Rear Spare Tyre Panel <i>Regis</i>	\$737.40	<i>x</i>
41	1	Rear Spare Tyre Panel Top Cover <i>Delnd</i>	\$260.40	✓
42	1	Rear Spare Tyre Panel Top Sponge <i>3x1</i>	\$206.00	<i>x</i>
43	1	Rear Spare Tyre Panel Sealant <i>1x</i>	\$450.00	<i>x</i>
44	2	Rear Spare Tyre Side Panel <i>Regis</i>	\$151.20	\$302.40 <i>x</i>
46	1	Rear Exhaust <i>Neu</i>	\$586.50	<i>x</i>
47	1	Rear Centre Exhaust <i>Neu</i>	\$562.40	<i>x</i>
48	1	Rear Exhaust Aluminium Cover <i>3x1</i>	\$95.00	<i>x</i>
49	2	Rear Exhaust Mounting <i>1x</i>	\$38.20	\$76.00 <i>x</i>

~~4282.40~~ SN. 2W Subtotal :- \$17,178.90
 3425.92

Labour charges

To remove & refit cushion & trim board	\$280.00 <i>60</i>
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To remove & refit rear LH & RH fender glass	\$200.00 <i>x</i>
Gum	\$100.00 <i>60</i>
To remove & refit reverse sensor	\$100.00 <i>50</i>
To remove & refit rear & centre exhaust	\$380.00 <i>x</i>
To repair rear chassis member	\$480.00 <i>x</i>
To check wiring	\$120.00 <i>30</i>

Towing fee	\$150.00 +
Tuff kote	\$150.00 60
Panel beating	\$3,000.00 1000
Spray painting	\$2,000.00 800 1200
	Subtotal :- \$7,130.00
	Total:- \$24,308.90

2630

Adrian Lj
 L/S 28/12/20
 07 days

total: 6255.92
 L/S: SK ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____