

TwinCar AUTOMOTIVE PTE LTD

Lee/Mr. Adam

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

K2LD BUILDERS
BLK 625 ANG MO KIO AVE 9 #02-94
SINGAPORE 560625

TP Chien.

Xiao Chen.

Contact : 84681818, 82366388

ESTIMATE

Repair Code : CLM15136

Date in : 22/12/2020

Vehicle Num. : SLR8387U

Model : TOYOTA COROLLA FIELDER HYBRID 1.5G AUTO

Chassis/Eng# : NKE1658037218/1NZ7977795

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Deformed</i>	1	681.90	<i>498</i> 681.90
FRONT BUMPER INNER SPONGE <i>cracked</i>	1	182.25	✓ 182.25
FRONT BUMPER LOWER UNDER COVER <i>Not new</i>	1	278.25	X 278.25
FRONT BUMPER SIDE RETAINER L/R <i>RH Dmgd</i>	2	171.75	<i>178</i> 343.50
FRONT RH FENDER <i>Buckled</i>	1	981.10	<i>599</i> 981.10
FRONT RH FENDER BRACKET <i>Bent</i>	1	84.90	✓ 84.90
FRONT RH FENDER INNER SHIELD <i>torn</i>	1	271.45	<i>185</i> 271.45
FRONT RH HEADLAMP ASSY <i>cracked</i>	1	2922.60	<i>1130</i> 2922.60
FRONT RH KNUCKLE ARM <i>Dmgd</i>	1	594.80	✓ 594.80
FRONT RH KNUCKLE ARM BEARING <i>2nd</i>	1	171.85	✓ 171.85
FRONT RH LINKAGE <i>Not new</i>	1	233.60	X 233.60
FRONT RH LOWER ARM <i>Bent</i>	1	1145.40	<i>478</i> 1,145.40
FRONT RH SHOCK ABSORBER <i>Bent</i>	1	561.60	✓ 561.60
FRONT RH SHOCK ABSORBER SPONGE <i>Not new</i>	1	89.90	X 89.90
FRONT RH SHOCK ABSORBER TOP MOUNTING <i>Not new</i>	1	271.75	X 271.75
FRONT RH STEERING TIE ROD END <i>Not new</i>	1	196.70	X 196.70
FRONT RH WHEEL HUB <i>Damaged</i>	1	389.90	✓ 389.90
FRONT STEERING RACK & PINION <i>Not new</i>	1	1955.40	X 1,955.40

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

K2LD BUILDERS
BLK 625 ANG MO KIO AVE 9 #02-94
SINGAPORE 560625

Contact : 84681818, 82366388

ESTIMATE

Repair Code : CLM15136

Date in : 22/12/2020

Vehicle Num. : SLR8387U

Model : TOYOTA COROLLA FIELDER HYBRID 1.5G AUTO

Chassis/Eng# : NKE1658037218/1NZ7977795

WASHER TANK <i>Debon-d</i>	1	189.80	✓ 189.80
WASHER TANK MOTOR <i>Neu Neu</i>	1	271.45	✓ 271.45
<i>5143.10</i> <i>3857.32</i> Subtotal before discount			11,818.10
Percentage discount 25%			2,954.53
Sub-total 1			8,863.58
FRONT BUMPER CLIPS - SET <i>Neu</i>	1	50.00	<i>20</i> 50.00
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>Neu</i>	1	50.00	<i>30</i> 50.00
FRONT RH SPORT RIM <i>ut</i>	1	750.00	<i>450</i> 750.00
FRONT RH TYRE <i>Neu Neu</i>	1	280.00	<i>X</i> 280.00
Subtotal before discount			1,130.00
Percentage discount 0%			0.00
Sub-total 2			1,130.00
Parts-total			9,993.58

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

300 ~~60.00~~
200 ~~320.00~~
80 ~~100.00~~
400 ~~800.00~~
400 ~~650.00~~

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

K2LD BUILDERS

BLK 625 ANG MO KIO AVE 9 #02-94

SINGAPORE 560625

Contact : 84681818, 82366388

ESTIMATE

Repair Code : CLM15136

Date in : 22/12/2020

Vehicle Num. : SLR8387U

Model : TOYOTA COROLLA FIELDER HYBRID 1.5G AUTO

Chassis/Eng# : NKE1658037218/1NZ7977795

To apply anti-rust chemical on repaired and replaced panel.

	1110	X 50.00
Labour Total		1,980.00
Parts & Labour Total		11,973.58

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5417.32

r/s : A.3K

05 Days.

A.3K

A.3K