



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1013/2020/NS
DATE : 29-Dec-20
WIP : 64390

VEHICLE IS IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR CHUA KAM TUCK
ADDRESS : 31 KEPPEL BAY VIEW
#05-92
SINGAPORE 098418
TELEPHONE : HP +65 92372628
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900022971
VEHICLE NO : **SMJ 3954 X**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 28/2/2019
ENGINE NO : CVK 076129
CHASSIS NO : WAUZZZF55KA024339
MILEAGE : 11853KM
DATE IN : 28-Dec-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Dec-20
PLACE OF ACCIDENT : GOLDEN MILE COMPLEX BASEMENT CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 3954 X

<u>S/N</u>	<u>NATURE OF JOBS</u>	<u>ESTIMATED CHARGES</u>	<u>SURVEYOR'S RECOMMENDATIONS</u>
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	X.
2	TO RENEW 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$ 300.00	✓
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$ 400.00	✓
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS.	S/N \$ 200.00 150	
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00	✓
SUB TOTAL LABOUR CHARGES		: \$ 2,660.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 3954 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00 ✓	
7	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00 ✓	
8	TO DISMANTLE REAR BUMPER, LHS REAR DOOR AND LHS SILL PANEL TRIM. TO RENEW LHS REAR DOOR AND LHS SILL PANEL TRIM. CUT OUT AND WELD LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,200.00 ?	
9	TO RESPRAY LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLE, LHS SILL PANEL TRIM, LHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 6,300.00	3125 Fender + associated parts = 3.5x550 = 1925 Door = 550 Sill panel trim 550 Door handle = 100
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 18,032.00	3125



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3954 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR FENDER - LH <i>dented</i>		\$ 2,472.00	✓
2 1/4 GLASS - LH <i>on</i>		\$ 709.00	✓
3 SIDE MEMBER TRIM - LH <i>del-d</i>		\$ 816.00	✓
4 SILL PANEL TRIM ATTACHMENT PARTS <i>?</i>		\$ 129.00	?
5 SILL PANEL TRIM ADHESIVE TAPES <i>new</i>		\$ 210.00	✓
6 REAR DOOR - LH <i>Distorted</i>		\$ 3,091.00	✓
7 REAR DOOR OUTER SEAL <i>on</i>	NEC	\$ 220.00	✓
8 BONDING AGENT <i>?</i>	NEC	\$ 47.00	?
9 CLEANING SOLUTION <i>?</i>	NEC	\$ 65.00	?
10 REAR DOOR ATTACHMENT PARTS <i>new</i>		\$ 128.00	X
11 REAR DOOR CATCH <i>?</i>		\$ 119.00	?
12 REAR DOOR SEAL - INNER LH <i>new</i>		\$ 582.00	X
13 DOOR HANDLE TRIM PLATE - LH <i>new?</i>		\$ 87.00	?
14 REAR DOOR TRIM - LH <i>new</i>		\$ 135.00	X
15 WINDOW REGULATOR - LH <i>new</i>		\$ 349.00	X
16 WHEEL HOUSING LINER - LH <i>new</i>		\$ 272.00	X
17 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>		\$ 167.00	X
18 1/4 GLASS SEALANT	S/N	\$ 100.00	✓
19 METAL FILLER POWDER	S/N	\$ 280.00	✓
20 STONE CHIP	S/N	\$ 180.00	✓
21 CAVITY WAX	S/N	\$ 140.00	✓
22 ACRYLIC SEALANT	S/N	\$ 180.00	✓
23 SUNDRIES <i>?</i>		\$ 300.00	?
TOTAL SPARE PARTS		\$ 10,778.00	
TOTAL LABOUR CHARGES		\$ 18,032.00	
GRAND TOTAL		\$ 28,810.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Adnan Lg
29/12/2017

Not Authorised, 13 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT