

Date: 28.12.2020
Vehicle No: SLH2524H
Model: TOYOTA AQUA HYBRID 1.5S
Chassis: NHP102568851-2016
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SDA1318A
Date of Accident: 27.12.2020

*NOT Authorised
L1 Rep &
Running After Paint*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>RM</i> \$848.70 ✓
2	REAR BUMPER SIDE BRACKET LH	1		<i>RM</i> \$64.40 ✓
3	REAR BUMPER REINFORCEMENT	1		<i>RM</i> \$590.60 X
4	REAR TAIL LAMP LH	1		<i>RM</i> \$530.20 ✓
5	REAR FENDER AIR VENT LH	1		<i>RM</i> \$55.80 X
6	REAR FENDER INNER LINER LH	1		<i>RM</i> \$129.60 X
7	REAR END PANEL	1		REPAIR
SUB TOTAL				\$2,219.30
LESS 25%				-\$554.83
PARTS TOTAL				\$1,664.48

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>RM</i> \$50.00 ✓
2	REAR BUMPER REVERSE SENSOR	1		<i>RM</i> \$300.00 X
3	REAR FENDER INNER LINER CLIPS LH	1		<i>RM</i> \$35.00 X
S/N TOTAL				\$385.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC. \$400.00 *200*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR END PANEL & ETC. \$500.00 *300*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$80.00 *20*

LABOUR CHARGES TO REMOEV & REPLACE REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR BUMPER. \$100.00 *50*

LABOUR TOTAL \$1,080.00

TingAn TOTAL \$3,129.48

Head office

6 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

