

Our Job Ref No : 305441430

Date : 22.01.21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. : SHA4450H CTPL

28.12.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **NTUC** --- **SMQ4247K**

2. The finalized amount shall be:

(a) Spare Parts after List discount **\$908.12**

(b) Labour Charges **\$750.00**

Total for Part-By-Part Repair Cost **\$1,658.12**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: **20%**

Final Lumpsum Repair cost

3. Estimated normal period for repairs: **2** working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.


We confirm the estimates and
finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Taufikh

Date : 27/1/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305441430
 REGN NO : SHA4450H
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 30.04.2019
 DATE/TIME IN : 29.12.2020 08:05
 ACCIDENT DATE : 28.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52	Cher ✓	
0002 04-01-0104-2532-G	BRACKET ASSY-RR BUMPER SI	1 L	55.80	20.00	44.64	? Xnn	
0003 04-01-0101-0111-G	I40VC BUMPER COVER CLIP R	10 L	22.00	20.00	17.60	her ✓	
0004 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1 L	451.25	20.00	361.00	ave ✓	932.65
0005 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	180.00	10.00	162.00	ant ✓	20% 746.12
							180
							10% 162
SUB-TOTAL :							952.76 908.12

JOB NATURE

0000 L	PANEL BEATING (repair rr fender Rh)	500.00	320		
0001 23-502	SPRAYPAINT ON AFFECTED AREA	450.00	400		
0002 20-22	REMOVE/REFIX REVERSE SENSOR	120.00	30	750	
SUB-TOTAL :					1,070.00 908.12
					750
					\$1658.12
					2 days #

Tanpin 97495244
 'wp' 29/12/2020 4pm
 P/P Kurnay before paint 2 days
 tanpin e lhambo.com

Danant

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 31.12.2020

Time: 14:53:42

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305441430
REGN NO : SHA4450H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 30.04.2019
DATE/TIME IN : 29.12.2020 08:05
ACCIDENT DATE : 28.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52
0002 04-01-0101-0111-G	I40VC BUMPER COVER CLIP R	10 L	22.00	20.00	17.60
0003 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1 L	451.25	20.00	361.00
0004 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	180.00	10.00	162.00

SUB-TOTAL : 908.12

JOB NATURE

0000 L	PANEL BEATING (repair rr fender Rh)	320.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	400.00
0002 20-22	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 750.00

TOTAL : 1,658.12

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :