

REF: AG2/200147211K

ASSIGNMENT

Veh No:

GBG1558R

Yr Regn:

06, 17

Bus / Van / Lorry / Taxi / Prime Mover /

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJA 7541K
Accident Date : 23-Dec-2020

Our Ref : 020189 (AGI) / CHAN

TEAM DECORAL PTE LTD
1 MOONSTONE LANE, #03-03
OH LENG BUILDING
Singapore 328462

No. : 06313

Date : 28-Dec-2020

PAGE : 1

Not Authorized
L1 Rep \$ 4450h
Murray After Paint
*6 days*ESTIMATED COST OF REPAIR FOR PEUGEOT PARTNER GBG1558R
=====

pc N/s tail door
pc N/s tail door "PEUGEOT" emblem
pc O/s tail door
pc O/s tail door "PARTNER" emblem
pc Tail door rubber
pc Rear bumper
pc Rear bumper reinforcement
pc Rear end panel

A 1,550.00 ✓
m 65.00 ✓
A 1,350.00 ✓
m 85.00 ✓
A 240.00 ✓ *50km 120km*
m 520.00 ✓
A 440.00 ✓
A 340.00 ✓

4,590.00
Less 10% : 459.00

pc Rear w/s glass sealant
pc Tail door 70km/h sticker
pc Tail door 6pax sticker

4,131.00 ✓
m 60.00 sn ✓
m 15.00 sn ✓
m 15.00 sn ✓

remove & refix rear windscreen
ss and conduct water leak test.

240.00 *160*

remove roof lining, front and
r seats, trim board and carpet

60.00 ✓

apply undersealing

60.00 ✓

putty and spray replaced parts

800.00 *600*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Con't Page 2 ...